| A MM DE OA DE State * Incident Date | 2020 1 20-0009423 000 Change Basic |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| B Location* | The B "Alternative Location Specification". Use only for Wildland fires. Census Tract 0015 - 03 |
| Rear of Apt./Suite/Room Directions | Waterloo IA 50701 - Zip Code irections, as applicable |
| C Incident Type * | Midnight is 0000 |
| 111 Building fire | Check boxes if Month Day Year Hr Min Sec |
| Incident Type | dates are the same as Alarm ALARM always required B 01 4 |
| D Aid Given or Received* | Date. Alarm * 02 04 2020 04:42:17 Shift or Alarms District Platoon |
| 1 Mutual aid received 2 Automatic aid recv. 3 Mutual aid given 4 Automatic aid given 5 Other aid given N None | CONTROLLED Optional, Except for wildland fires Controlled LAST UNIT CLEARED, required except for wildland fires Special Studies Local Option |
| F Actions Taken * | G1 Resources * G2 Estimated Dollar Losses & Values |
| 11 | njuries N None Not Mixed Solution use 2 Propane gas: <21 lb, tank (as in home BBQ grill) Not Mixed Assembly use 2 Medical use Medical use |
| EMS-6 HazMat-7 Wildland Fire-8 X Apparatus-9 X Personnel-10 Arson-11 U Unknown J Property Use* Civilian Civilian Required for Confirency Unknown Structures | 4 Kerosene: fuel burning equipment or portable storage 4 Diesel fuel/fuel oil: vehicle fuel tank or portable 5 Diesel fuel/fuel oil: vehicle fuel tank or portable 6 Household solvents: home/office spill, cleanup only 7 Motor oil: from engine or portable container 51 Row of stores Enclosed mall 8 Bus. & Residential Office use Industrial use |
| 131 Church, place of worship 161 Restaurant or cafeteria 162 Bar/Tavern or nightclub 213 Elementary school or kindergarte 215 High school or junior high 241 College, adult education 311 Care facility for the aged 331 Hospital Outside 124 Playground or park 655 Crops or orchard 669 Forest (timberland) 807 Outdoor storage area 919 Dump or sanitary landfill 931 Open land or field | 342 Doctor/dentist office 361 Prison or jail, not juvenile 361 Prison or jail, not juvenile 419 1-or 2-family dwelling 429 Multi-family dwelling 439 Rooming/boarding house 449 Commercial hotel or motel 459 Residential, board and care 464 Dormitory/barracks 519 Food and beverage sales 936 Vacant lot 938 Graded/care for plot of land 946 Lake, river, stream 951 Railroad right of way 960 Other street 961 Highway/divided highway 962 Residential street/driveway 579 Motor vehicle/boat sales/repair 579 Motor vehicle/boat sales/repair 579 Motor vehicle/boat sales/repair 571 Gas or service station 579 Motor vehicle/boat sales/repair 571 Gas or service station 579 Motor vehicle/boat sales/repair 571 Gas or service station 579 Motor vehicle/boat sales/repair 571 Gas or service station 579 Motor vehicle/boat sales/repair 571 Gas or service station 599 Business office 615 Electric generating plant 819 Livestock/poultry storage(barn) 882 Non-residential parking garage 891 Warehouse 984 Industrial plant yard Lookup and enter a Property Use code only if you have NOT checked a Property Use box: Property Use 111 Bowling establishment NFIRS-1 Revision 06/03/05 |

| K1 Person/Entit | ty Involved | Business name (if a | oplicable) | | 319 - 23 Area Code Phon | 1 - 4554 e Number |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Check This Box if same address as incident location. Then skip the three duplicate address lines. More people inv | Mr., Ms., Mrs. First Number Post Office Box IA 50703 State Zip Code olved? Check th: | Name Prefix Street or Hi | Apt./Suite/Room | Wilson Last Name Waterloo City Forms (NFIRS-1S) as | | Suffix |
| K2 Owner Same as | person involved? | 11-11 | | | | |
| Then che | ck this box and skip of this section. | Business name (if Ap | plicable) | | 319 - 23 Area Code Phon | 1 - 9461 e Number |
| Check this box if same address as incident location. Then skip the three duplicate address lines. | Mr., Ms., Mrs. First 1029 Number Post Office Box IA 50702 State Zip Code | Name Commerce Comm | | Beschorner Last Name Waterloo City | | Suffix ST treet Type Suffix |
| L Remarks | | | | | | |
| At approximately Waterloo Fire (Wheard radio traf #4 located at 12 Dispatch and stathree people and University Avenuthat a reporting WFR 300 Command page the remaind building with he line and make an up a supply line scene. WFR 334 p WFR 300 responde commercial build of masonry block insulation. The insulation and sarriving units t WFR 300 witnesse incident address | FR) Station fic from WFR 00 Ansboroughted that a manage waterloo, party has can instructed deser of fire unavy black smootheir are ersonnel assessed code 3 from ing constructed. The roof is interior of ignificant coopside to witch to well d heavy smokes | #1 Headquarte Engine 304 A n Avenue Wate ale subject a ple Lanes on Iowa 50701 an alled and sta ispatch to up nits to this oke exiting b nterior attac rival. WFR Me isting WFR 30 m Station #1. ted of type 2 s mostly flat the building eiling space WFR Tac chann e while respon | rs located a cting LT. Mirloo, Iowa. rrived at st fire. Maples d is near WH ted there is grade the cascene. WFR 3 oth sides of k through a dic unit 3344 on the ext Upon WFR 30 construction with a rubk is known to above the suel #2 on arr | the Spence who we spence had contation #4 and sation #4 and sation #4. It is lots of smoke the roof. WFR (Bravo) side do responded with erior of the but of arrival, I found the exterior of the exterior er membrane, shave a drop ceil spended ceiling ival. | treet Waterlows assigned tacted Black aid that he alley is loop Dispatch information the area will building at a sign of the second of the sec | to Station Hawk County was robbed by cated at 2608 ormed WFR g fire and ingle-story ll a hose truck to set aged on single-story constructed and foam lown dvised and the |
| L Authorization | | | | | | |
| LUCK, T officer in charge Check Box if PETERSEN, | e ID Signatu | rsen, Ben | BC Posit | ion or rank Assignme | | 2 04 2020 |
| same as Officer Member making repair charge. | port ID Signatu | re | Posit | on or rank Assignme | ent Month | n Day Year |
| | | | | | | |

MM DD YYYY

07009 IA 2 4 2020 1 20-0009423 000 Narrative

FDID * State Incident Date * Station Incident Number * Exposure *

Narrative:

At approximately 04:39 hours on 02/04/2020 I (WFR 300-WFR Battalion Chief Troy Luck) was at Waterloo Fire (WFR) Station #1 Headquarters located at 425 E. 3rd Street Waterloo, Iowa. I heard radio traffic from WFR Engine 304 Acting LT. Mike Spence who was assigned to Station #4 located at 1200 Ansborough Avenue Waterloo, Iowa. Spence had contacted Black Hawk County Dispatch and stated that a male subject arrived at station #4 and said that he was robbed by three people and they set Maple Lanes on fire. Maples Lanes Bowling Alley is located at 2608 University Avenue Waterloo, Iowa 50701 and is near WFR Station #4. Dispatch informed WFR that a reporting party has called and stated there is lots of smoke in the area.

WFR 300 Command instructed dispatch to upgrade the call to a commercial building fire and page the remainder of fire units to this scene. WFR 304 reports arriving at a single-story building with heavy black smoke exiting both sides of the roof. WFR 304 will pull a hose line and make an offensive interior attack through a (Bravo) side door. Second truck to set up a supply line on their arrival. WFR Medic unit 334 responded with 304 and staged on scene. WFR 334 personnel assisting WFR 304 on the exterior of the building.

WFR 300 responded code 3 from Station #1. Upon WFR 300 arrival, I found a large single-story commercial building constructed of type 2 construction. The exterior walls are constructed of masonry block. The roof is mostly flat with a rubber membrane, sheet metal, and foam insulation. The interior of the building is known to have a drop ceiling with blown insulation and significant ceiling space above the suspended ceiling. WFR 300 advised arriving units to switch to WFR Tac channel #2 on arrival.

WFR 300 witnessed heavy smoke while responding in the area of University Avenue and the incident address. WFR 300 found thick, black and charged smoke exiting from the entire structure and openings. Heavy smoke is discharging through roof vents and roof area. WFR 300 conducted a drive around 360 size-up of the structure on arrival. WFR 300 noted no building openings located on the Charlie side of the building. WFR Engine 304, Medic 334, Engine 306 and Waterloo Police Department (WPD) are on scene. WPD is securing the scene and conducting law enforcement work. WFR 304 has parked in the parking lot and is located on the buildings Bravo side. WFR 304 is advancing a 1 ¾ inch line into the Bravo side entry door near the alpha/bravo corner of the building. Engine 306 is securing a supply line from a hydrant located on Thorndale Avenue to Engine 304 with a 5" supply line. WFR 300 assigned Medic 334 with stretching a 2 ½ inch line from Engine 304 and provide the line to 304's crew inside the building. WFR 304 would report heavy fire in the Alpha/Bravo corner of the building with fire extension into the suspended ceiling space. WFR 304 is extinguishing the fire.

According to Weather Underground, at 04:54 hours they report a temperature of 25 degrees, 63% humidity, wind from the North at 13 mph, 0 precipitation and the sky conditions were cloudy for Waterloo, Iowa on February 4th 2020.

It should be noted that the description of the property and identification system used in this report is applied in a clockwise manner with the front of the building facing University access road as Alpha side, the side of the building facing Thorndale is Bravo side, the rear of the building facing Hartman Avenue as Charlie side, and the remaining side facing Chalmers Avenue is Delta side. Command would eventually be established on the Alpha side of the building. There are distant exposures on the Charlie and Delta sides.

WFR 300 assigned WFR 306 Acting Lt. Marc Mahood with conducting a 360-degree size-up around the building on foot. This was to specifically look for a possible Fire Department Sprinkler

Narrative:

Connection on the exterior of the building. WFR 306 Mahood would later report back no FDC or sprinkler system and no other obvious issues. WFR 300 tasked WFR 306 with closing the buildings Natural gas service. WFR 306 would later report the gas valve closed. WFR 300 requested dispatch to contact Mid American for service disconnection. Mid American responded and disconnected power. They also locked out the gas meter on the Alpha side of the building. WFR Engine 306 was then assigned to lay their remaining 5" supply line to the alpha/delta corner of the building for WFR Ladder 311. WFR 302 also assisted with laying 5" supply to 311. After 306's task of supply to 311, they were assigned RIT. RIT would later be assigned to WFR 302 and Hudson Fire at different points throughout the incident. Waterloo Water Works was requested to shut down domestic water supply. WFR 306 then found the domestic water supply main valve in a alpha side utility room and turned it to the closed position. Waterloo Water Works arrived and was no longer needed.

WFR 300 assigned 311 with taking a position on the buildings alpha/delta corner to be able to ladder the roof and protect the delta side exposure if needed. After 311's arrival, they were tasked to take a 2 ½ inch hose line into the interior through the alpha side/delta corner entry door for offensive fire attack. This area of the roof contains significant smoke exiting the structure under pressure. WFR 311 would eventually make their way along the interior alpha side and toward the center and Bravo side of the building. WFR 311 reports the majority of fire toward the alpha side interior and ceiling area.

Upon WFR Engine 301's arrival, WFR 300 assigned 301 to a position on the buildings Charlie/delta corner on Wilbur avenue and Janney Avenue. WFR 300 assigned them to make an interior offensive attack through the delta side and Charlie corner access door. WFR 301 was later assisted and backed up by engine 303 and engine 305. Supply was established with these units on a hydrant located at Wilbur and Janney. WFR 301 would later report that they are not finding fire in the charlie/delta corner and smoke visibility has increased in the area of the bowling lanes.

WFR 300 assigned Medic unit 334 with pulling a hose line and making access to the building's bravo side and Charlie corner access door for offensive fire attack and investigation for fire conditions. WFR 334 made entry and reported light smoke and found a basement area that they searched and found no fire. It should be noted that WFR 300 advised all units to check the suspended ceiling space for fire while advancing into the structure.

WFR requested additional WFR engines to respond to the scene. WFR 302 arrived and assisted WFR 311 with supply and in the alpha/ delta corner of the building. WFR engine 305 arrived and backed up 301 and 303 in the building's Charlie/delta corner.

WFR 300 determined from unit reports that the fire was mostly contained but is going to require more man power and resources to hold and improve current operations and conditions. WFR 300 requested mutual aid from Cedar Falls, Hudson and Evansdale. WFR 300 requested dispatch to have mutual aid units respond to level two staging located at the old Hardees' parking lot and the corner of Falls Avenue and University Avenue and Stephan Avenue. Mutual aid radio TAC channels were patched. Upon Cedar Falls 521 arrival, WFR 300 assigned him to Staging Officer and gave him incident channel #9 for communications. WFR 300 contacted dispatch and requested the Black Hawk County EMA contact me for the request of the American Red Cross for firefighter rehab assistance. The Red Cross did eventually respond and was set up with WFR Medic 334 on the alpha side of the structure parking lot and was rehab. Crews were initially required to refill SCBA's from Engine 301 at the charlie/delta corner of the building. The Technical Rescue Trailer with air cascade would later be requested and placed

at the building's alpha/bravo corner and used to refill SCBA's. Mutual aid crews would also be requested and received from Gilbertville and Raymond.

WFR 300 made contact with WFR off duty Battalion Chief Mike Moore by phone and requested him to respond to WFR Station #1 and start personnel call back to cover the rest of the city. Chief Moore responded to Station one and handled the rest of the city including providing 9 extra WFR personnel for this incident and responding to the scene with the technical rescue trailer for cascade air system use.

WFR 300 called off duty WFR Battalion Chief Ben Petersen and requested him to respond to the scene for incident command assistance. Chief Petersen would later take over this incident after shift change. This would be his normal shift. Chief Petersen would arrive at incident command and provide assistance with chief's aid duties concerning operations, scene command, organization and management, radio monitoring and staging.

WFR 300 attempted to contact WFD Chief Pat Treloar concerning this incident. I was unable to contact him the first time. The second time I attempted to call him, I realized he was already sitting behind me in the back seat of WFR 300. Chief Treloar took on information gathering, and Public Information Officer. Chief Treloar made contact with the owners on scene. WFR Chief Treloar also contacted WFR Fire Marshal Chris Ferguson and Fire Inspector Brock Weliver for assistance with the fire investigation.

WFR crews reported still dealing with heavy fire in the building's alpha/bravo corner WFR 306 was moved up from RIT and assigned an attack line and to make entry on the alpha side and bravo corner entry door for fire control. WFR 304 moved from the Bravo side and backed up 306 in the indicated area. WFR 311 removed their 2 ½ line from the building and redeployed into the alpha side main entry near the alpha bravo corner and on the other side of the interior wall from 306 and 304. The area is identified as the Pro Shop in the facility. WFR 302 would be moved to RIT.

Cedar Falls Fire (CFR) responded with 521, Engine 501, Engine 502, and Ladder 511. WFR assigned CFR 521 with Staging Officer. WFR 300 assigned CFR 501 to make entry and back up 311 and 302 in the alpha/delta corner of the building. CFR 501 did not make entry, but assisted with hose line. WFR 300 assigned CFR 502 to make entry and back up WFR 334 and 306 in the bravo/charlie corner. CFR 502 did not make entry on this corner. WFR 301 would later state CFR 502 was in the building with them on the charlie/delta corner at one point in time. WFR 300 assigned CFR 511 to make roof access on the building's bravo side. CFR 511 would later report that they are in the area but cannot get close enough to the building due to hose lines to and from 304 blocking access. WFR 300 assigned CFR 511 to move up to the alpha side near WFR 300 and set up to make access to the alpha/bravo corner for a roof report. CFR 511 did not move to this location and fill the assignment however, CFR 502 used a ground ladder instead. CFR 502 made access to the roof and provided a roof report. CFR 502 departed the roof. CFR units were cleared from the scene by WFR 300.

WFR units report the building's roof structure may be compromised in the alpha/bravo corner. WFR 300 assigned WFR 311 to deploy the aerial ladder for a roof report from their location. WFR 311 would later report that the roof looks intact with the exception of a small area at the alpha/bravo corner. There is a change to the roof structure in this area. WFR 311 cannot tell if its normal or from fire damage. WFR 300 assigned CFR 502 to deploy a ground ladder to the Bravo side to gain roof access and egress for a roof report. Another ground ladder was

placed on the delta side wall for access and egress. CFR unit 502 was assigned to assess the roof area for fire extension. CFR 502 made roof access and reports that the roof is designed to slope down in the alpha/bravo corner. There is some discoloration and the roof feels soft by CFR 502 report. CFR 502 ordered to exit the roof. WFR 300 cleared all CFR units from this incident. WFR 306 and WFR 308 (308 is an assembled unit from extra WFR personnel arriving on scene) made roof access and cut a section of the roof that contained discoloring. They found fire extension into the roof layer system. WFR 306 and 308 extinguished the fire in that area. Later, 306 would cut more roofing in the same area during fire overhaul. A hose line was supplied to the roof for these operations. Units operating inside under this roof area were ordered out of the area.

When it became clear that the fire was contained, WFR cleared and thanked mutual aid units for their assistance. It should be noted that Raymond Fire and others responded and provided drone assistance. This allowed WFR 300 Command to monitor roof operations and assess FLIR images of the building.

WFR Training Officer Lt. Dave Jensson arrived on scene and was assigned as Safety and Accountability Officer. During roof operations Lt. Jensson informed WFR 300 of a structural issue concerning the bravo side exterior wall. WFR 300 momentarily departed command and assessed the bravo side wall. The upper section of the exterior bravo side wall is leaning inward and displays cracked and broken motor and block with an inward tilt. This is near the area of roof support damage in the alpha bravo corner. The bravo side wall issue extends form the alpha/bravo corner and runs over half way down the bravo side wall. WFR 300 advised all crews on scene including WPD and the building owners of this condition. The front of the building was taped off by WPD. WFR operating in these areas were advised not to enter these areas as possible. The large main steel roof supports run across alpha to charlie walls. Bravo to delta wall roof supports are significantly smaller.

The size of this incident includes the actions of many units and personnel. This report is of WFR 300's account. Please see individual unit and any individual reports including other agency reports for further information. Fire cause and determination was requested and turned over to WFR Fire Marshal and Fire Inspectors. Please see WPD investigative reports. No responder injuries were reported during this incident.

It is my (WFR 300) opinion through education, experience and the facts of this case that the origin of fire is inside the interior of the buildings alpha side main entry area and alpha/bravo corner areas. The fire grew from this point and extended upward and outward inside the building. There is extensive fire, heat and smoke damage throughout the building with the heaviest damage in the alpha side main entry area and alpha/bravo corner. The fire damage decreases as you move away from this identified area. Please see fire investigative report for further investigative information and fire origin and cause determination. This fire was extinguished by fire personnel.

During light fire overhaul, the owners of the building were escorted by WFR and WPD to the external openings of the structure so that they may look into the building and assess the extent of damage to their business. The owners did not enter inside the building. They returned to their vehicles after their exterior assessment.

As fire operation needs decreased, units were cleared from the scene and WFR shift change had taken place. Scene command was transferred from Battalion Chief Troy Luck to Battalion Chief

WATERLOO FIRE RESCUE 07009 02/04/2020 20-0009423

Ben Petersen. WFR BC Luck cleared the scene and returned to WFR station #1. BC Petersen remained on scene and conducted further operations.

On scene during the incident, I was contacted on scene by Ryan Wilson. Ryan is identified as the General manager of this business. He stated that the owner Rich Eighme was currently in Portugal. I was also approached on scene by another owner Zac Beschorner. I quickly updated them of current fire operations. Later Chief Treloar would make contact with them and other owners that were on scene.

WFR BC Troy Luck

The following report is drafted by WFR Battalion Chief Ben Petersen. It was completed on 2-4-2020

On 2-4-2020 at 05:08:00 hours I received a cell phone call from Captain Harter informing me 2608 University Avenue, Maple Lanes, was on fire. I began to arrange to respond to the scene from my residence. I then received a phone call from on scene shift commander Battalion Chief Troy Luck at 5:23:00 hours and informed him I was responding directly to the scene to assist.

At 05:34:00 hours I arrived to scene and reported directly to Unit 300, BC Luck where he briefed me of incident details. Operations were in the Offensive strategy. Unit 300 was positioned on the Alpha (front) side of the structure in the parking lot of the business. I took a position inside Command Unit 300 with BC Luck. I performed Chief's aid duties for BC Luck assisting with scene command, operations, organization and management, radio monitoring, and staging.

A personnel scene size up was performed. I viewed a one story brick Type II commercial structure approximately 300 x 500 feet with moderate to heavy smoke showing from the Alpha side of the structure. Heavy pressurized smoke observed issuing from a presumable vertical vent over the kitchen area. The structure is block and wood construction. Multiple WFR units are actively involved in interior attack of the structure. Weather is clear night conditions with temperatures at or below 20 degrees.

Mutual Aid departments were directed to Level II stage at Stephan St. and Falls ave. parking lot. Unit 521 placed in charge of staging. Responding departments with various resources and number of personnel were: Evansdale, Raymond, Hudson, Cedar Falls, & Black Hawk Emergency Management.

Battalion Chief Moore and Captain Harter performed Waterloo Fire Rescue personnel call backs and managed city operations at Fire Headquarters.

The main body of fire was located in the Bravo / Alpha area of the structure. Interior fire attack proved successful in fire containment and extinguishment. Multiple hand lines were in operation. Ventilation was performed naturally horizontally by existing structure openings. Unit 311 ladder was directed to set up and recon all roof conditions from ladder basket. Rehab was set up with Unit 334 on the Alpha side and crew recycles were initiated. A request



was made for the Technical Rescue trailer to be brought to the scene for air supply. Rec Cross arrived to the scene to assist.

Unit assignments and reassignments were issued ongoing throughout the duration of the incident. Rapid intervention Crew assignments were in place throughout the duration of the incident.

Fire Overhaul was initiated after fire control was achieved. Roof structure showed evidence of being compromised in the Bravo / Alpha area of the roof along with the Bravo side exterior block wall. All personnel on scene informed. Extensive overhaul was required.

Fire Chief Treloar arrived to scene to assist at command post. He conducted information gathering and liason and Public Information Officer duties. Waterloo PD assisted with scene security, information gathering, interviews, and investigation to alleged criminal activity involving the incident. Fire Marshal Ferguson on scene and Fire Inspector Weliver.

Shift transfers conducted by Command Staff for personnel from B shift to C shift between the time of 07:30:00 hours and 07:45:00 hours. The scene was transitioned from Overhaul to Investigation at approximately 09:00:00 hours. Waterloo PD began to process scene and evidence in conjunction with fire investigations and processing. At approximately 0800 hours the owner and manager were escorted to all exterior doors on the Bravo, Alpha, and Delta side to observe from the exterior the damage to the interior of the structure. At approximately 10:00:00 hours Command staff began to release fire unit's back to service and stations. The owners were updated approximately hourly on operating stages of the incident. At approximately 10:00:00 hours Battalion Chief Luck released from the scene and incident command transferred to Battalion Chief Petersen. I cleared the scene at 11:45:38 hours transferring command to last remaining engine company Unit 304, Lt. Dahlhauser. Fire watch was set up approximately hourly throughout day. Unit 304 advised to conduct fire watch at 21:00:00 hours. The building was secured and no evidence of smoke or steam was detected.

This report was drafted on 2-4/5-2020 by Battalion Chief Ben Petersen. All information contained is documented to the best of my recollection of the facts and events.

The following is written by WFR Fire Chief Pat Treloar-On-2-4-2020 at approximately 0539 hours I received a call from WFR Captain Bill Harter. Captain Harter informed me that there was a working fire at Maples Lanes on University Avenue. I responded to the fire scene from my residence. I arrived on scene and immediately reported directly to WFR Command 300. BC Petersen was assisting BC Luck with command and control activities. Fire Control had been obtained, and mutual aid units were preparing to leave the scene. I functioned as the PIO and gathered information from builder owner as well as Waterloo PD. I made contact with Fire Marshal Ferguson and requested him to report to the scene. After all media agencies had received information I left the scene to assist with city operations.

WATERLOO FIRE RESCUE 07009 02/04/2020 20-0009423

Chief Treloar

| A | MM DD YYYY 07009 | Y)20 | 1 20-0009 Station Incident Num | | * E: | 000 kposure | - Henange | NFIRS -2 Fire |
|----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------------|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| B B1 | Property Details [Not Residential] Estimated Number of residential living units building of origin whether or not all units became involved | ín | C On-Site Materials or Products Enter up to three codes. Or more boxes for each code On-site material (1) | Check | amo agr Pro | Bu Pi | f there were any signifer commercial, industrial, all products or material whether or not they because the storage or warring or manufackaged goods for apair or service | energy or s on the ame involved ame involved ahousing acturing |
| B 2 | 001 Buildings not involved Number of buildings involved None | l | On-site material (2) | | 1 2 3 4 1 1 2 | Pr Pa Re | alk storage or war cocessing or manuf; ackaged goods for spair or service alk storage or war cocessing or manuf; | acturing sale shousing acturing |
| D | Acres burned (outside fires) Less than one acre Ignition | 1 | Cause of Ignition Check box if this is an exp Skip to section G | osure | 3 4 report. | Re | ackaged goods for appair or service 3Human Factors Contributing To | Ignition |
| | Area of fire origin * UU Undetermined Heat source * | U | Intentional Unintentional Failure of equipment or h Act of nature Cause under investigation Cause undetermined after actors Contributing | n inve | estigatio | | 1 Asleep 2 Possibly imparatorn alcohol or dru 3 Unattended per 4 Possibly ment 5 Physically Dis 6 Multiple person | None ired by ags son al disabled sabled |
| D3 | UU Undetermined E2 | 2 [0 [L | DO Factors actor Centributing To Ignition (| 1) | _ | one | 7 Age was a fact Estimated age of person envolved 1 Male | 2 Female |
| F1 Bran Mode Seri | equipment Involved d | Equipme 3 Equipme 1 2 ctable byed by | Equipment Power | G | Ente | er up | to three codes. n factor (1) | ors None |
| H ₁ 1 [2 [3 [| Mobile Property Involved Not involved in ignition, but burned Involved in ignition, but did not burn Involved in ignition and burned | proper | in multiple locations, and so no tools to install. Property Type & Ma | ke | | Loca So th fr Ar Po Co | 1 Use Pre-Fire Plan Av me of the information pr is report may be based to om other Agencies son report attache lice report attach roner report attach her reports attach | resented in apports and added |
| L | oblie property model icense Plate Number State VIN No | umber | Year | | | | NFIRS-2 Revision | 01/19/99 |

| I1 Structure Type * In Fire was In enclosed building or a | 2 Building Status * | | I4 Main Floor Size* NFIRS-3 |
|--------------------------------------------------------------------------|---------------------------------------------------------|----------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| portable/mobile structure complete | | Height Count the ROOF as part | Fire |
| the rest of this form 1 [X] Enclosed Building | Under construction | of the highest story | |
| 2 Portable/mobile structure | 2 X Occupied & operating | | |
| 3 Open structure | 3 Idle, not routinely used 1 Under major renovation | Total number of stories | , 022 , 708 |
| 4 Air supported structure | Vacant and secured | at or above grade | |
| 5 Tent | 5 Vacant and unsecured | 001 | OR |
| 7 Underground structure (work areas) | Being demolished | Total number of stories | |
| 8 Connective structure (e.g. fences) | Other | below grade | Lenght in feet Width in feet |
| O Cother type of structure | J Undetermined | | 20.9.0 10 20002001 20 2000 |
| J ₁ Fire Origin * J ₃ | Number of Stor. | ies K Mat | cerial Contributing Most |
| _ ~~~ | Damaged By Fla | | Flame Spread |
| Below Grade Coun | it the ROOF as part of the hi | - Cliec | k if no flame spread ame as material first ignited Section I |
| Story of fire origin | Number of stories w/ minor of | 0.77 | ame as material first ignited Section L |
| J ₂ Fire Spread * | (1 to 24% flame damage) | K1 | 11 |
| 1 Confined to object of origin | Number of stories w/ signif (25 to 49% flame damage) | cant damage | contributing most to flame spread |
| 2 Confined to room of origin | Number of stories w/ heavy o | 272.00 | 9 |
| 3 Confined to floor of origin | (50 to 74% flame damage) | IN2 | Parity of the same |
| 4 X Confined to building of origin | Number of stories w/ extreme | most (| of material contributing Required only if item contributing code is 00 or<70 |
| 5 Beyond building of origin | (75 to 100% flame damage) | | |
| L1 Presence of Detectors * | L3 Detector Power | Supply L5 Det | cector Effectiveness |
| (In area of the fire) | I I Destroy only | Req | uired if detector operated |
| N None Present Skip to section M | 1 Battery only 2 Hardwire only | 1 MAlert | ed Occupants, occupants responded |
| 1 X Present | 3 Plug in | 2Occup | ants failed to respond |
| U Undetermined | 4 Hardwire with bat | | were no occupants |
| o _ onde definitied | 5 Plug in with batte | ery 4 Faile U Undet | d to alert occupants |
| L2 Detector Type | 6 Mechanical 7 Multple detectors | | GIMINGU |
| 4 1977 - 1 | power supplies | | ector Failure Reason |
| 1 X Smoke | 0Other | Require | d if detector failed to operate |
| 2 Heat | U X Undetermined | 1 □ Pause | failure shutoff or disconnect |
| 3 Combination smoke - heat | L4 Detector Opera | tion I - H | per installation or placement |
| 4 Sprinkler, water flow detection | 1 Fire too small | _ | - |
| | to activate | - | of maintenance, includes cleaning |
| 5 More than 1 type present | 2 Operated (Complete Section | | ry missing or disconnected |
| 0 | 3 Failed to Oper | ate 0 Dother | ry discharged or dead |
| U Undetermined | U X Undetermined | U Undet | |
| | | | |
| \mathbf{M}_1 Presence of Automatic Extinguishmen | 1.20 | ic Extinguishment | M5 Automatic Extinguishment |
| N X None Present | Required if fire | Operation was within designed range | System Failure Reason Required if system failed |
| 1 Drogent | te rest | & effective (Go to | M41 |
| M ₂ Type of Automatic Extinguishment S | 2 Doperated | & not effective (| 1 System shut off 2 Not enough agent discharged |
| Required if fire was within designed ra | ange of AES 3 Fire too | small to activate | 2 Agent discharged but did |
| 1 Wet pipe sprinkler | 4 Failed t | o operate (Go to M5 | not reach fire |
| 2 Dry pipe sprinkler | U Undeterm | ined | 4 Wrong type of system |
| 3 Other sprinkler system 4 Dry chemical system | | | 5 Fire not in area protected 6 System components damaged |
| 5 Foam system | M4 Number | of Sprinkler perating | 7 Lack of maintenance |
| 6 Halogen type system | | system operated | 8 Manual Intervention |
| 7 Carbon dioxide (CO ₂) system 0 Other special hazard system | 100,022.00 12 | -3 | 0 OtherU Undetermined |
| | | | |

WATERLOO FIRE RESCUE 07009 02/04/2020 20-0009423

| A | 07009 FDID * | I. Sta | | | 4 | YYY 2020 | 1 Stal ron | | -0009423 | | NFIRS - 9 Apparatus or hange Resources |
|----|------------------------|-----------|------------------------------|----------|--------------------------|----------------------|---------------------------|------|--------------------------|--------------------------------------------------------------------------------------------|----------------------------------------|
| ВА | pparatus o Resource | or * | | Check if | and T | | Hour Min | Sent | Number of * People | Use Check ONE box for each apparatus to indicate its main use at the incident. | Actions Taken |
| 1 | ID 300 |] I | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 04:42 04:46 11:45 | X | 2] | Suppression EMS Other | |
| 2 | ID 301 Type 11 | I | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 04:42 04:47 11:24 | X | <u> 3 </u> | Suppression EMS Other | |
| 3 | ID 302 | 1 | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 04:55 05:04 11:45 | x | [3] | Suppression EMS Other | |
| 4 | ID 303 | 1 | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 04:42 04:49 07:55 | x | <u>[3</u>] | Suppression EMS Other | |
| 5 | ID 303 Type 11 | I | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 08:11 08:17 10:17 | X | [3] | Suppression EMS Other | |
| 6 | ID 304 Type 11 | 1 l | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 04:42 04:44 11:59 | X | <u> </u> | X Suppression EMS Other | |
| 7 | ID 305 Type 11 | I | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 05:02 05:12 10:53 | x | 3] | X Suppression EMS Other | |
| 8 | ID 306 | | Dispatch Arrival Clear | | 2 4 2 4 2 4 2 4 | 2020 2020 2020 | 04:42 04:46 11:18 | x | 3 | Suppression EMS Other | |
| 9 | ID 311 Type 12 | | Dispatch Arrival Clear | | 2 4 2 4 2 4 | 2020 2020 2020 | 04:42 04:50 10:47 | x | 2 | Suppression EMS Other | |

| | MM DD TALL A LINCIDENT DATE & | YYYY 2020 1 Station | | -0009423 | | NFIRS - 9 Apparatus or hange Resources |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|--------------------------------|-------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| B Apparatus or * Resource | Date and Check if same as Month Day | alarm data | Sent | Number of * People | Use Check ONE box for each apparatus to indicate its main use at the incident. | Actions Taken |
| 1 ID 324 Type UU | Arrival 2 | 4 2020 07:45 4 2020 07:56 4 2020 17:05 | X | 1 | Suppression EMS Other | |
| 2 ID 326 | Arrival 2 | 4 2020 07:45 4 2020 07:56 4 2020 17:05 | x | 1 | Suppression EMS Other | |
| 3 ID 334 Type 76 | Arrival 2 | 1 2020 04:42 4 2020 04:45 1 2020 11:02 | X | 2] | X Suppression EMS Other | |
| 4 ID | Dispatch Clear Clear | | | | Suppression EMS Other | |
| 5 ID Type | Dispatch | | | | Suppression EMS Other | |
| 6 ID | Dispatch C Clear C C | | | | Suppression EMS Other | |
| 7 ID | Dispatch | | | | Suppression EMS Other | |
| 8 ID Type | Dispatch | | | | Suppression EMS Other | |
| 9 ID Type | Dispatch Clear Clear | | | | Suppression EMS Other | |
| Type of Apparatus Ground Fire Suppre 11 Engine 12 Truck or aerial 13 Quint 14 Tanker & pumper of 16 Brush truck 17 ARF (Aircraft Res 10 Ground fire suppre Heavy Ground Equip 21 Dozer or plow 22 Tractor 24 Tanker or tender 20 Heavy equipment, Aircraft 41 Aircraft: fixed w 42 Helitanker 43 Helicopter 40 Aircraft, other | combination combination coue and Firefighting) ression, other ment other | Marine Equipmed 51 Fire boat was 52 Boat, no put 50 Marine appart Equipmed 61 Breathing as 62 Light and as 60 Support appart Medical & Res 71 Rescue unit 72 Urban Search 73 High angle 75 BLS unit 76 ALS unit 70 Medical and | with pump imp iratus, coment ipparatus ir unit caratus, scue ch & resc rescue i | other s support other cue unit | Other 91 Mobile co 92 Chief off 93 HazMat ur 94 Type 1 ha 95 Type 2 ha 99 Privately 00 Other app NN None UU Undetermi | ommand post ficer car nit and crew and crew y owned vehicle paratus/resource |

| A 07009 | MM DD YYY LIA 2 4 2 State * Incident Date * | (Y 020 1 304006 | | 0009423 | 000 Exposure * | Delete | TRS - 10 ersonnel |
|------------------------------------|---------------------------------------------------|--------------------------------------------------|-------------|-----------------|----------------------------------------------------------------------|-----------------|-------------------------------------------|
| B Apparatus or Resource | Check if same as ala | rm dat | x | appara a | Use ONE box for each atus to indicate in use at the ent. | List up to | s Taken o 4 actions apparatus personnel. |
| 1 ID 300 Type 91 | Dispatch | 2020 04:42 2020 04:46 2020 11:45 | Sent X | 2 i | Suppression EMS Other | L_ | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| LUCK, T PETERSEN, BEN | Luck, Troy Petersen, Ben | BC BC | X X | | | | |
| 2 ID 301 Type 11 | Dispatch X 2 4 Clear 2 4 Clear | 2020 04:42 2020 04:47 2020 11:24 | Sent | <u>3 </u> | Suppression EMS Other | | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| AGBESE, O ERNST, S HELLER, J | Agbese, Onyotse Ernst, Scott Heller, Josh | EF-4 ENG-BS LT BS | X X X | | | | |
| 3 ID 302 Type 11 | Dispatch 2 4 | 2020 04:55 2020 05:04 2020 09:08 | Sent | <u></u> 3 □ | Suppression EMS Other | | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| ANDERSON, N HESS, S WEBER, B | Anderson, Nick Hess, Samuel Weber, Benjamin | PM-8 FF-8 FF-1 | X X X | | | | |

| A 07009 FDID * | MM DD YYYY 1A 2 4 2020 State * Incident Date * | 1 200 a+ Loan | | 0009423 | 000 Exposure | Delete | FIRS - 10 ersonnel |
|---------------------------------------|-------------------------------------------------------|------------------------|-------------|--------------------------------------|--------------------------------------------------------------------------|-----------------|-------------------------------------------|
| B Apparatus or Resource | Check if same as alarm data | Hours/mins | [X] | Number of * Check appar its n indic | Use ONE box for each matus to indicate which is at the lent: | List up t | ns Taken o 4 actions apparatus personnel. |
| 1 ID 303 | Dispatch | 04:49 | Sent X | 3 | Suppression EMS Other | | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| BJERKE, J HENNESSY, B MEISER, D | Bjerke, Jerry Hennessy, Bob Meiser, David | PM-8 FF-8 PM-6 | X X X | | | | |
| 2 ID 303 | Dispatch X 2 4 2020 Arrival 2 4 2020 Clear 2 4 2020 | 08:17 | Sent | | Suppression EMS Other | | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| BJERKE, J HENNESSY, B MEISER, D | Bjerke, Jerry Hennessy, Bob Meiser, David | PM-8 FT-8 PM-6 | X X X | | | | |
| 3 ID 304 Type 11 | Dispatch X 2 4 2020 Arrival 2 4 2020 Clear 2 4 2020 | 04:44 | Sent | 3 | Suppression EMS Other | L | |
| Personnel ID | Name | Rank or Grade | Attend X | Action Taken | Action Taken | Action Taken | Action Taken |
| PALMER, J | Hansen, Randall Palmer, Jeff Spence, Michael | FF-4 ENG-10 FF-8 | X X X | | | | |

| A 07009 | MM DD YYYY IA 2 4 2020 State Incident Date | 1 Starton | | 0009423 Number * | 000 Exposure | Delete | FIRS - 10 Personnel |
|-----------------------------------------|---------------------------------------------------------|-------------------------------|-------------|---------------------|-----------------------------------------------------------|-----------------|----------------------------------------|
| B Apparatus or Resource | Check if same as alarm data | Hours/mins | [x] | appar | Use ONE box for each atus to indicate ain use at the ent. | h List up t | o 4 actions apparatus personnel. |
| 1 ID 305 | Arrival 2 4 2020 | 0 05:02 0 05:12 0 10:53 | Sent | <u></u> 3 □ | Suppression EMS Other | | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| PHILLIPS, J ROTH, C SAMUELSON, B | Phillips, Jason Roth, Christopher Samuelson, Bart | ENG-BS FF-4 LT BS | X X X | | | | |
| 2 ID 306 | Arrival 2 4 202 | 0 04:42 0 04:46 0 11:18 | Sent | <u> </u> | Suppression EMS Other | | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| HEYERHOFF, S MAHOOD, M STEWART, B | Heyerhoff, Stephen Mahood, Marc Stewart, Brian | ENG-10 FF-8 FF-1 | X X X | | | | |
| 3 rp 311 | Arrival 2 4 202 | 0 04:42 0 0 04:50 0 10:47 | Sent | 2 - | Suppression EMS Other | | _ |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| BARGMAN, J LEE, K | Bargman, Jared Lee, Kevin | ENG-BS CF | X X | | | | |

| A 07009 | MM DD YYYY IA 2 4 2020 State A Incident Date A | 1 1 | 20- | 0009423 | 000 Exposure | Delete | FIRS - 10 Personnel |
|----------------------------|--------------------------------------------------|-------------------------------------------|--------|--------------------------------------|--------------------------------------------------|-----------------|-------------------------------------------|
| B Apparatus or Resource | Check if same as alarm de | | x | Number of * Check appar its n incid | Use: ONE box for eace that to indicate the lent. | h List up t | ns Taken o 4 actions apparatus personnel. |
| 1 ID 324 | Arrival 2 4 20 | 020 07:45 020 07:56 020 17:05 | Sent | 1 _ | Suppression EMS Other | L | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| FERGUSON, C | Ferguson, Chris | EM | X | | | | |
| 2 ID 326 | Arrival 2 4 20 | 020 07:45 020 07:56 020 17:05 | Sent | L 1 [| Suppression EMS Other | L. | ⅃ |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| WELIVER, B | Weliver, Brock | LT BS | X | | | | |
| 3 ID 334 Type 76 | Arrival 2 4 20 | 020 04:42 020 04:45 020 11:02 | Sent | 2 - | Suppression EMS Other | | |
| Personnel ID | Name | Rank or Grade | Attend | Action Taken | Action Taken | Action Taken | Action Taken |
| PAUL, D ZIMMERLY, M | Paul, Dwight Zimmerly, Michael | PM-1 PM-1 | X X | | | | |

Unit Notify Time Enroute Time Arrival Time Cleared Time
300 Command Vehicle 04:42:17 04:44:09 04:46:54 11:45:38

Staff ID\Staff Name Activity Rank Position Role
LUCK, T Luck, Troy L Fire At Scene Battalion C
PETERSEN, Petersen, Ben Fire At Scene Battalion C

Unit Narrative

BEN

See main narrative

301 Engine 301 04:42:17 04:43:52 04:47:55 11:24:59

| Staff ID\ | Staff Name | Activity | Rank | Position | Role |
|-----------|--------------------|---------------|-------------|--------------|--------------|
| AGBESE, O | Agbese, Onyotse W. | Fire At Scene | Firefighter | Firefighter | Fire Fighter |
| ERNST, S | Ernst, Scott | Fire At Scene | Engineer ba | Engineer | Fire Enginee |
| HELLER, J | Heller, Josh | Fire At Scene | Lieutenant | Fire Lieuten | Fire Lieuten |

Unit Narrative

301 arrived on scene and was directed by 300 to position at the "Charlie-Delta" corner on Janney St. We positioned our truck at Janney and Wilbur. We found heavy smoke coming out of an open single walk-in door on the Delta-Charlie corner. We connected a supply line to the hydrant next to 301 and deployed a 2 k" attack line for entry. We used bolt cutters to cut a fence between the building and a parking lot to get the attack line to the building. As personnel were flaking hose out along the Delta side to ease in advancing into the building, I made my way to the door to check conditions. I could see heavy smoke but no fire inside the building. I closed door to slow the flow path while we prepped for entry. I closed the door too far and it latched shut. Once the line was set up and charged, FF Agbese and I manned the attack line with 303's crew while FE Ernst remained with 301 to pump and refill SCBA. We used a halligan to force the door back open. With the door open, we began advancing our attack line. We entered and moved along the

With the door open, we began advancing our attack line. We entered and moved along the Delta wall towards the Alpha side. It was a walkway that went alongside the bowling lanes. We stopped every 20' to pull a couple ceiling tiles from the drop ceiling to check for extension. Once we reached the start of the bowling lanes, about the way through the building, we found 302's crew advancing a hose line as well. We turned and headed toward the Bravo side and worked our way across the bowling platform. As we continued checking behind the ceiling tiles we were finding approximately a 10 degree increase at every opening. We were still finding heavy smoke and moderate heat conditions, but no fire. As we advanced toward the Bravo side we stretched our hose line about 1/3 of the way across building and we were advised from the crews feeding hose at the door that we were out of hose. At this point 301 needed to refill with air, so we exited the building and returned to 301 for more air.

After refilling with air we returned back to the building and returned to the nozzle of our attack line. There we found 305's crew. Once there we found the smoke had lightened up at the floor level so we were able to walk. 305 and our crew left our hose line and headed toward the Alpha side from our current position. As we got up on the main walkway we found another 2 ½" attack line that a crew had left. We picked it up and advanced it toward the area were 304 had found and extinguished fire. This area was the check-in and pro shop area. Once we reached that area we found several hot spots still burning. We used the 2 ½" to extinguish those hotspots. As we tried to move closer we found that line to also be stretched out as far as it could. We looked around the check in area and found a 1 ¾" attack line that we picked up and took into the check in area. Once in the check in area we found several more hotspots and a small fire in a back closet like area. Once those fires were extinguished we found heavy fire and rollover coming over the wall in the back

D7009 IA 2 4 2020 1 20-0009423 000 Responding Units/Personnel

closet area. We extinguished the rollover as 311 advised that they found entry into a room adjacent to the closet area that was the cause of the fire and rollover. Once the closet fire was extinguished we needed to refill our SCBA with air again. 301's crew exited the building and returned to 301.

After refilling with air FF Agbese took some rehab at 301 while I joined up with 305's crew and reentered the building. We were tasked with searching the Charlie end of the building for extension. We entered again through the Delta Charlie door. We split into two groups to search. I was with FE Phillips. As we searched the Charlie end behind the pin setting machines we realized the machines were still energized and parts were spinning. We radioed command who advised that MidAmerican was working on the power. After talking with command, we located a main electrical disconnect at the Charlie Delta corner. We turned the power switch off that shut down power to the machines. We continued our search and found no extension to the Charlie end. We met back up with the second group at the Bravo Charlie corner.

We were then assigned to check the Alpha side for any active fire. We reentered through the Bravo Charlie corner and made our way to the Alpha end of the building. We searched the Bravo end to the Delta end. We found HVAC and wiring had collapsed from the ceiling, blocking the walkway in front of the check in counter. We crawled through the blockage and continued our search. We found no new fire along the Alpha end. We exited the building at the Delta Alpha corner and returned to 301.

After returning to 301 I regrouped with EF Agbese and we were assigned to report to the Alpha side of the building and take over RIT. We reported to the Alpha Bravo corner at RIT. While performing RIT we assisted with ventilation and overhaul in the Alpha Bravo corner. There appeared to be no hotspots in the Alpha Bravo corner so overhaul was limited and we remained with natural ventilation to vent the building. After performing RIT for a while command advised that we could clear the scene and return to Station 1 to switch out with the oncoming shift. We returned to Station 1 for crew swap. While there we filled 301's cascade and all the spare bottles we had on the truck. After everything was aired back up we turned the truck over to C shift.

- Lieutenant Heller

C Shift

Once 301 cascade was refilled 301 went back to the scene. 301 staged on university access in the 2700 block. Our first assignment was to shut down the supply line to 311. 301,302,304 all worked together to reload it back onto 307(302). There was one section of 5" that was run over, it was rolled and not reloaded onto 307. It was placed on Engine 301 to take to station 3 for testing. After this undertaking was complete we were tasked with locating the haligan/flathead axe off engine 301 that remained in the building when 301 B shift needed to retreat to refill air tanks. After seaching it was located on the Delta side at the at the start of the alley closest to the D wall. With the tools returned to 301 shift member on scene gathered and assignments handed out. Next we were to shut down supply to Engine 4 and reload onto Engine 6. When completed Engine 301 went to the CD corner to retrieve 650' of 2 1/2 into 301 Acting Lt's pickup truck. With another assignment complete 301 returned to the Alpha side to meet with command, command released 301 to return to quarters. 301 returned to service and headed to headquarters. After arriving 301 needed to have cascade refilled to full, 2 1/2" have reloaded. 301 took 5" to station 3 for testing, and then took a tested 5" to station 2 to be loaded onto 307. Engineer / Acting LT Sean Schott

302 Engine 302 04:55:58 04:57:23 05:04:57 09:08:57

| Staff ID | Staff Name | Activity | Rank | Position | Role |
|-------------|-----------------|---------------|-------------|--------------|--------------|
| ANDERSON, N | Anderson, Nick | Fire At Scene | Paramedic 8 | Firefighter/ | Paramedic |
| HESS, S | Hess, Samuel J | Fire At Scene | Firefighter | Firefighter/ | Fire Fighter |
| WEBER, B | Weber, Benjamin | Fire At Scene | Firefighter | | |

D7009 IA 2 4 2020 1 20-0009423 000 Responding Units/Personnel

 Unit
 Notify Time
 Enroute Time
 Arrival Time
 Cleared Time

 302 Engine 302
 04:55:58
 04:57:23
 05:04:57
 09:08:57

Staff ID\Staff Name Activity Rank Position Role

Unit Narrative

Engine 302 called to the scene by 300 as an additional engine company. Just prior to arrival on scene, 302 crew was directed to catch a hydrant. We were able to connect to the hydrant near the corner of Chalmers Ave. and the University access road, and lay a 5 inch supply line into Aerial 311. After laying the supply line, we were directed to assist Captain Lee advance a 2 1/2 inch attack line into the structure via a doorway in the alpha/delta corner to aid in extinguishment. Upon entering the structure we encountered moderate smoke which was banked down about 2/3 of the way to the floor and very little heat. We advanced the 2 1/2 inch line several feet into the structure along the delta wall, but we did not encounter any active fire. We came within a few feet of 301's crew who was advancing an attack line from an opposite direction along the same wall.

We were directed to back our attack line out of our current position, redirect it through the kitchen and into the bar area. We advanced our 2 1/2 inch line through the bar area and into the main walking area of the structure that ran parallel with the alpha side. We met 304's crew while completing this task. We had to back out and replenish our SCBA's at that point. We filled SCBA tanks via 301's cascade system, and returned to the alpha side to wait for another assignment.

We were assigned to assist Captain Lee in repositioning our 2 1/2 inch attack line into the main front doors because other crews had encountered heavier smoke and fire conditions. We assisted in extinguishment of some fire near the pro shop area, but had to leave shortly after that to refill our SCBA's again. Upon returning from filling our SCBA's, we were directed to be the Rapid Intervention Crew (RIC). There was already RIC equipment placed on the sidewalk near the door at the alpha brave corner.

After our RIC assignment, we were directed to assist other crews inside of the pro shop and front desk area. We assisted 305's crew as well as Firefighters Jon Kieler, Kyle Fuller, and Jim Mayer with location and extinguishment of any fire that we encountered. We did pull ceiling and extinguish a small amount of fire in the area which was just inside the front doors. We exited at the request of 300. During this assignment, and prior to our exit, we found a wallet sitting on a shelf inside the bar area. We did not disturb the wallet, and I reported this finding to command face to face.

We were directed by 300 to do a recon of as much of the structure as we could while avoiding the bravo side of the building. 302 crew made our way through the front doors, made a right turn, followed the main walkway that ran parallel to the alpha side towards the delta wall. After making to the delta wall, we walked into the very back, mechanical area. We pulled ceiling tile every 30 to 40 feet to do a visual inspection for active smoke or fire, and used our thermal imager to get a heat temperature reading. We never encountered any active smoke or fire, and we did not get a temperature reading above 95 degrees Farenheit. These findings were also reported to command face to face.

Shortly after finishing our recon assignment, we were relieved by 302 'C' crew, and we returned to station 2.

Report Completed by: Acting Lieutenant,

Nick Anderson

-302 C Shift Shift Change LT. B. Shannon, FERO E. Schmudlach, TB B.Peters

302 C shift was called in by BC. B.Tetersen to come and relieve B Shift personal at the Scene. C Shift 302 crew was at Station 2 and members (Siglin, Schott, B.Peters) who were on Q310 came back from the fire at the above location of Maple Lanes. Oncoming Shift Personal of Shannon, Schmudlach and B.Peters were then told to respond back to the scene to relieve B Shift 302 Members. 302 C shift arrived on scene and were ordered to make contact w/ 302 B shift and get briefed and change out personal. Once Briefed by Acting Lt. Nic Andersen C shift personal Lt.Shannon made contact with TC Luck/Petersen and were given orders to break down the 2.5 inch hand line that was coming from A311 and into the Alpha side front doors. 302 broke down the 2.5 inch and then were asked to get 302 back in service after loading the Alpha Side Supply Line of 5 inch from the corner of Chalmers and the frontage road to the A311. 302 and 301 and 304 assisted in loading up 302's 5 inch. Once back loaded a Call for a Residential Smoke Alarm came in from Jill St and 302 was dispatched via IC. 302 went En Route to Jill Code 3 and duties were ended at Maple Lanes.

LT. B.Shannon

303 Engine 303

04:42:17

04:43:34

04:49:57

07:55:49

| Staff ID\Staff Name | Activity | Rank | Position | Role |
|---------------------------------|---------------|-------------|--------------|-----------|
| BJERKE, J Bjerke, Jerry Alan | Fire At Scene | Paramedic 8 | Engineer | Paramedic |
| HENNESSY, B Hennessy, Bob John | Fire 41 Scene | Firefighter | | |
| MEISER, D Meiser, David Michael | Fire A. Scene | Paramedic 6 | Firefighter/ | Paramedic |

Unit Narrative

Dispatched: 303 responded with the initial general alarm to Maple Lanes. While en route, Dispatch advises RP was a walk-in at Fire Station 4 informing them Maple Lanes is on fire. 304 gave their size up stating heavy smoke showing on both sides of the building. 300 gave the 3rd arriving assignment to set up on Janney to pull 2.5. 303 arrived just behind 301 on Janney.

Arrival: 303 announced our arrival and Incation on Janney. Smoke is showing out the roof vent and 2 entry doors along the "D" wall. Double door mid "D" wall was partially open, I opened it further could see heavy smoke near the floor, closed the door. PD officer was present advising there was a burglary here tonight. The door was locked when I went to try to open it a second time.

303 advised command we are going to assist 301 with advancing 2.5 hand line and I was sending 303 engineer to assist 311 crew. 303 crew assisted 301 with advancing hand line and monitoring inspection holes in the ceiling with TIC. 305 took over to allow 303 make a bottle change. 303 returned to continue to advance line until reached the end. Then assisted 311/302 with advancing and repositioning their 2.5 hand line.

300 reassigned us into the incident to walk the interior of the "B" wall to look for possible caused of light smoke showing at the roof line. Advised command clear can visualize the bottom of the roof sheathing. With 306 found small hotspots around where the main body of fire had been. Began to overhaul the storage area then relieved by 308 crew. Command reassigned us to assist with breaking down hose for 301 then return to station 3 for personnel change.

Shift transfer was made approximately 0800 at Station 3. 300 wanted returning personal to bring 333 also.

Lt J. Powers

| Unit | Notify Time | Enroute Time | Arrival Time | Cleared Time |
|----------------|-------------|--------------|--------------|--------------|
| 303 Engine 303 | 08:11:18 | 08:11:18 | 08:17:00 | 10:17:51 |

| Staff ID\Staff Name | Rank | Position | Role | |
|---------------------------------|---------------|-------------|--------------|-----------|
| BJERKE, J Bjerke, Jerry Alan | Fire At Scone | Paramedic 8 | Engineer | Paramedic |
| HENNESSY, B Hennessy, Bob John | Fire At Scene | Firefighter | | |
| MEISER, D Meiser, David Michael | Fire At Scene | Paramedic 6 | Firefighter/ | Paramedic |

Unit Narrative

07:55:50 B-shift crew gave report of the incident and of tools used off of 303 that were used during the incident, air packs and bottles that needed refilling and what had been left at scene which consisted of Flat head axe, unknown location.

08:00:00 Advised by BC Moore by phone call to return to scene with 303 and 303 after tools and equipment rechecked on 303.

08:11:00 Unit 303 and 333 returned to the scene

08:17:00 Unit 303 and 333 arrive on scene and advised command. Was told to report to 300 for assignment. 303 Crew of Bjerke, Hennessy, and Mieser was given a task of entering the building on the A-B corner and look for how spots and smoldering items that may need to be removed from the building. 303 Crew entered building on the A side in the B corner door and used thermo imagining camera to look for elevated areas of heat and any signs of smoke. Was met by 305 crew and assisted them with some removal of sheet rock along the interior side of the A wall at the ceiling and used 1 %" hose line that was left inside to cool hot spots. Returned to the outside of the building and was met with 300 and assigned task of beginning to reload hose unto engine 304. Engineer Hennessy began refilling spare bottles and air packs off of 303 as Acting LT Blacke and firefighter Meiser began loading 2 12" hose to the back of 304, began breaking down 2 6" line that ran to the B-C corner of the building along with 1 %" line and rolling it up for transport back to the station to be thawed and reloaded unto 306. After hose was loaded and rolled, 303 crew met with 300 command and was tasked with starting P.P.V. fan along the A side middle door and then to stand by until other crews completed operations and to be available to take other calls throughout the city as needed. After meeting with all crews and command was advised to return to quarters. Advised 300 and other units that flat head axe with orange strip had not been found as of this time. 303 returned to service.

304 Engine 304 04:42:17 04:42:26 04:44:36 11:59:29

| Staff ID\Staff Name | | Antivity | Rank | Position | Role | |
|---------------------|---------|-----------|---------------|-------------|-------------|--------------|
| HANSEN, R | Hansen, | Randall J | Fire At Scene | Firefighter | Firefighter | Fire Fighter |
| PALMER, J | Palmer, | Jeff | Fire At Scene | Engineer 10 | Engineer | Fire Enginee |
| SPENCE, M | Spence, | Michael | Fire At Scene | Firefighter | Firefighter | Fire Fighter |

Unit Narrative

On Tuesday 02/04/2020 I heard the doorbell at station 4 rings at approximately 0430 hrs. I got up and went to the front door where I saw a car parked on the apron in front of E-304 as I was looking out the door an older white male approached the door. I could hear his saying "I have an emergency" I opened the door and he stated that he was the janitor at Maple Lanes and that he had been robbed and assaulted. I asked if he had called 911. He stated that he did not because he did not have a phone. I told him to come in and that I would call dispatch. That's when he told me that there were three people who assaulted him. That's when he told me "then they set the place on fire"

FF Hansen walked out to the apparatus floor and 1 told him to wake everyone up that there is possibly a fire at Maple Lanes. I then grabbed a portable radio from E-304 and relayed this information to dispatch and I either said make this a call or make this a general alarm and show us en route.

Upon arrival at Maple Lanes we approached from the east side of the building on the access

road, entered the parking lot and drove to the west side of the building so I could at least get a view of three sides of the building. I had D/E Palmer spot E-304 on the west side of the building. I reported heavy black smoke coming from both sides of the building. There is a steel, single walk in door on the Alpha/Bravo corner of the building that had pressurized smoke coming from it. The double glass walk in doors on the Bravo side of the building was dark and I could not see anything through them because of the smoke. I had FF Hansen pull an 1 % attack line and asked D/E Palmer after he got us water to flake out a 2 1/2 inch line for arriving crews to back us up with. I advised 300 that I was making entry through the bravo side door and that it was locked and I would be breaking glass to gain entry. I broke the glass in the door, reached in and unlocked the door. We encountered another set of glass doors a few feet in. Those doors were unlocked. FF Hansen and I advanced the hose line through a lot of downed ceiling, wires, duct work and debris for approximately 30 feet until we found fire above us at the front desk area. FF Hansen started putting water on the fire that was above us and the counter where we were at. I radioed 300 and advised him that we had fire in the A/B corner and that we were knocking it down. I also advised him to let incoming crews know of the hanging wires and debris. FF Hansen and I then moved further behind the front desk area to another room/office where we found more fire. At this time I contacted 300 and advised we would be exiting the building to replenish our air bottles. FF Hansen and I exited the building through the Bravo side door where we had entered and got our bookies switched out by D/E Palmer. We then went back into the structure and continued fighting fire where we had left off from in the back office. We got to the back of the office area and I felt like we should be where the steel walk in door that I referenced earlier should be at, but there was no other door in that room. We backed out of that room and started to advance along the wall trying to find access to another room. Our alarms went off on our air packs and I advised 300 we would again be exiting to replenish air.

Other crews have arrived on scene and are soing what they were assigned to at this point so I had a face to face with 300 telling him what we had encountered and what we had done so far and that we were going to make our way to E-301 to fill our air tanks.

Upon replenishing our air FF Hansen and I again entered through the Bravo side door and resumed where we had left off from. Now that visibility had improved FF Hansen and I found our way to the Pro Shop area where we were able to extinguish several spot fires in the three rooms of the Pro Shop. We also saw that the ATM machine at the front desk was heavily damaged, the door had been forced open and the money box/tray seemed to have been removed. We then exited the building through the main entrance and encountered E-306's crew. Act. Lt. Mahood pointed out where the "I" be mad in the ceiling are warped and twisted. We then got a pike pole and entered through the walk in door on the Alpha/Bravo corner with E-306's crew to pull ceiling at the request of **OO.** I pulled ceiling in that portion of the room from the door to the back of the room. I'F Hansen extinguished some boxes of shoes in that area as well.

After exiting that room I was standing at the Alpha/Bravo corner I felt that I could see the Bravo wall bowing out. I called Lt. Junsen over to verify what I was seeing. We agreed that it was bowed and that some block but moved above the door and that there was a crack running down brick of the A/B corner. Lt. Jensen reported this to 300. 300 then requested that FF Hansen and I ladder the Delta side of the build so crews on the roof had a safe means of egress due to the integrity of the Bravo side wall compromised. We got a 24' extension ladder from 311 and placed it on the Delta side. I then advised 300 that task was complete.

E-304's reliefs arrived on scene. We each gave our reliefs a turn over as to what had been done so far. I made a face to face with all and advised our reliefs were here and had been updated. 300 the released us from the scene. D/E Palmer, FF Hansen and I walked back to station #4. Act. Lt. Spence

| O7009 | IA | 2 | 4 | 2020 | 1 | 20-0009423 | 000 | Exposure | Units/Personnel

| Unit | Notify Time | Enroute Time | Arrival Time | Cleared Time |
|----------------|-------------|--------------|--------------|--------------|
| 305 Engine 305 | 05:02:41 | 05:04:34 | 05:12:31 | 10:53:17 |

| Staff ID\Staff Name | Activity | Rank | Position | Role |
|-------------------------------|---------------|-------------|--------------|--------------|
| PHILLIPS, J Phillips, Jason | Fire At Scene | Engineer ba | Engineer | Fire Enginee |
| ROTH, C Roth, Christopher L | Fire At Scene | Firefighter | Firefighter | Fire Fighter |
| SAMUELSON, BSamuelson, Bart C | Fire At Scene | Lieutenant | Fire Lieuten | Fire Lieuten |

Unit Narrative

305 dispatched at the request of 300 at 05:02 hrs. 305 arrived on scene and attempted to try to stage on Thorndale, but relocated to Janney Ave. due to Thordale being blocked by supply line. 305 was assigned by Command Lo assist 301 and 303 with 2 4" line that was pulled in the C-D Corner walk in door. Hoon entry 303 and 301 needed to exit to refill on air. We were updated as to where they had advanced and that the ceiling is being opened and checked every 10' to confirm no fire above us. It. Powers advised that the walk in door was opened a small amount on the D-A corner for escape. We advised Command of this. FF Roth and I continued to advance finding minimal rise in the ceiling temperature as we opened it and moved toward the B-Side from the front area of the A-side of the building. Engineer Phillips was feeding us hand line and then moved up to our position with mutual aide FF that assisted him. We found small areas of Lire in the A side pro-shop area. We worked on hot spots. Capt. Lee had reached our area of extinguishment and as 301 was working on hot spots he found fire behind the glass door in the bowling ball display area. Phillips and I had control on the 2 by time as Roth broke the right side glass door with a pike pole and we knocked down the fire. 305 crew then needed to exit to fill SCBA's. We refilled SCBA's and with Lt. Heller 305 crew requested from Command to check for extension in the ceiling along the C-Sidn. We did not find anything remarkable. Lt. Heller and Engineer Phillips found main panel and short down the power. Command then requested we work our way back checking the A-side cerling. Higher heat noted in area directly above the fire but no sign of active fire in calling. We did extinguish hot spots behind the counter in the main entrance and removed the counter top to the front desk area. The bar and cafe area were unremarkable and checked bathrooms and locker rooms to confirm they were empty. We then advised that we needed to exit for SCBA refill. Upon our SCBA's being refilled and a shurt break we were requested by Command to assist 308 crew by going in the A-B walk in door. We were advised they were working on hot spots. 305 crew assisted them in this area. Upon 303 needed to exit for air, 302 joined us. We continued where 308 left off extinguishing hot spots and overhauling. Act. Lt. Nick Anderson found an area in the ceiling emitting smoke from between the roof truss and metal ceiling approximately20' in from the exterior main door. 305 and 302 crews worked to open and cool the area. The area flared up as it was opened, we continued to cool it with Phillips on a hand line and Roth working with pike pole. 306 also assisted, upon not being

Engine 305 C Shift: Lt Troy Resor, Engineer Toda Moudry, Firefighter Onazi Agbese 305B shift returns to the station and personnel are switched out. B shift gives us a run down of equipment used and its status on the truck. The 301 Lt mask is out of air and the spare bottles are in use at the scene. All other equipment is accounted for and on the truck. C shifts crew then leaves the station and goes to HQ where we refill the mask and are sent to the scene. We arrive on scene and report to command. 305 is tasked with entering the A-B corner of the structure with a line and checking for any other hotspots. We find a small amount of smoke coming from the ceiling and roof line upon entering the structure. Capt. Mahood is already in the structure and we use the line to put water on the area. This decreases it significantly. We then get a ladder and pike pole and pull insulation out from the corner where the roof meets the wall. There are no embers or

able to open the ceiling enough from inside to confirm complete extinguishment I updated Command face to face with BC Luck. BC limit took visual from the A-side main door with me. 305 again needed to refill SCBA's. Upon being retilled Command sent us back to Station 5 to

change out with C Shift. 10-7 and turned over to C-Shift at 08:05 hrs. B. Samuelson

07009 IA 2 4 2020 1 20-0009423 000 Exposure Units/Personnel

flames present but still a small amount of lingering smoke. We then report this to command who already has a crew working on the roof area. Command states they will have them check it out. We then continue to overhaul the A-B corner of the structure until we can find no more smoke. We then exit the structure and are reassigned to the roof to open up the A-B corner to see if the fire has extended into the roof and parapet wall area. We open the area and find smoke trapped between the structure and the brick facade. We remove several lengths of trim from the wall and find no extension. Once completed we return to the ground and have a regrouping of all crews with 300. We are then assigned to work on reloading the trucks with hose before being released to return to quarters. 305C shift 10-8

306 Engine 306

0/1:42:17

04:43:09

04:46:12

11:18:06

| Staff ID\Staff Name | Act Erity | Rank | Position | Role |
|--------------------------------|---------------|-------------|--------------|--------------|
| HEYERHOFF, Sheyerhoff, Stephen | Kira At Scene | Engineer 10 | Engineer | Fire Enginee |
| MAHOOD, M Mahood, Marc | Fire At Scene | Firefighter | Firefighter | Fire Fighter |
| STEWART, B Stewart, Brian | Fire At Scene | Firefighter | Firefighter/ | Fire Fighter |

Unit Narrative

306 were called to maple lanes for a commercial building fire. 304 arrived on scene first and reported smoke showing. Upon 306 arrival we found a hydrant on Thorndale. 306 laid a 5" supply line to engine 304 that was located on the bravo side of the building. 306 opened the hydrant when 304 called for water. 306 then was tasked with doing a 360 to look for a FDC connection on the building. Once that was completed it was reported to 300 that there wasn't one. 306 then began to pull a 2 1 to the door on the Bravo/Charlie corner. 306 were then tasked with getting a supply line to 311. 306 crew located a hydrant at the corner of Chalmers and University access. 302 arrived and laid the 5" to 311 while 306 waited at the hydrant until 311 called for water. 306 then was tasked with RIT. We were at the alpha / bravo corner close to 300. I shat off the gas main that was located on the alpha side. The manager arrived on scene and I went with him to make sure all of the doors that could be unlocked from the outside were unlocked. We were unable to unlock the walk door on the alpha side of the alpha / bravo corner meause he did not have a key for it. The owner showed up a short time later and had the key. When the door was unlocked there was heavy smoke coming out of the door. 306 was smen tasked with fire attack through the same door. Once inside we encountered high heat and zero visibility. There was shelving with shoes and bowling balls, 306 were able to advance through the room and put out a significant amount of fire before running low on air. Once our air was replenished went back inside for more fire attack and overhaul. There were a 40% of hor spots on the shelving in the storage area for the pro shop. 306 were asked to check the kitchen and bar area for fire extension above the ceiling. We pulled the drop coiling in several different areas and found nothing. 306 found the main water shut off for the building in a utility room and shut it off. During overhaul in the pro shop it was a scovered with the TIC that there was significant heat at the metal roof deck. When water was applied it would only cool it momentarily. It was then determined that we needed to open the roof up to extinguish the fire. 306 and 308 got on the roof and found an area that had burned through the rubber membrane. We cut a roughly 12x12 area of the rubber membrane with the K-12 saw then removed the 3 inches of insulation to get to the metal deck. We found some smoldering insulation that we extinguished but no active fire. 306 gar back down from the roof and reported to 300 what was found. 306 B shift was then relieved by 306 C shift.

Acting 306 Lieutenant Marc Mahood

2-4-2020 306 C shift

O7009 IA 2 4 2020 1 20-0009423 000 Responding Units/Personnel

We came into work and were picked up by the suburban and taken down to relieve B shift at the Maple lanes fire.

Once we were on sight we met up with B305 and took their gear that we needed and got our new assignment from 300B shift.

We first filled our SCBA off of Trailer and then made entry into the B side main entrance in the middle. We went in with Dave Jensen and were to look for fire extension and any other hazards. We didn't make it far the HVAC system fell not far form the door way. We then went down stairs which hadn't been chacked. We forced the door open with a haligan Bar and search the basement. It was full of water about a foot deep. There was no fire extension but the ceiling tiles had fallen to the stairwell and walls had heavy smoke damage. We exited the building and made entry into a door for the storage room on A side in the A-B corner. There we found heavy fire damage both in the ceiling and through the room that extended through the maintenance room and in to the Pro Room in the front. We found a fire in the maintenance room where they bore and drill the balls. There we used the 1 % to extinguish and then overhauled the wall and around to check for extensions. We made it out to the Sales room and search again and found no further extension of fire. Our hose stopped at this point and we again went back through the same entrance searching through the rubble for any signs of fire.

Once we were out of that room we got a second assignment as RIT team for about 20 minutes. Third assignment was to tear into a well and find where the smoke was coming from. It wasn't in the wall so we were asked to no to the roof and make a trench cut along the parapet wall and find out if any fire extension was in that space. We made a cut just to the left side of the main entrance on the A side or towards the B side. There we ended up with a hole about 4 x4 feet to find clean material that had not been exposed to heat. We then took the flashing off the A side of the building and found smoke pockets in between the walls and roof holding smoke. This is what where we found most of the smoke we were seeing from the cracks and holes in the wall. We also pulled back the rubber roof to expose the materials to check for fire extension. Once this aired out the smoke seemed to subside a lot and disappear eventually. We then gathered all the tools and equipment that was brought up to us on the roof and make our way down and off the roof. Once off the roof were given the next task and that was to help load hose on the engines being dismissed from the scene.

We did load hose on 304, 306, and 311. Once done with that we loaded up our tools, they were the RIT tools and ladder. We got the truck organized and ready for service leaving 304 the only truck with hose lines off of it. We did switch nozzles off their truck with others because they got closed by accident and froze.

We were released from the scene to go back to our station and get something to eat and drink and change cloths if needed. We then dropped approximately 200 feet of 2 ½ that was frozen hose at station to thaw. We were asked to come back and relief 304 when done. We then made it back down to Maple lanes and ended up just loading their hoses and doing a clean up of equipment to make them ready to respond to other call. They had 1 ¾ off, 2 ½, and Five inch that was actually out hose off 306.

When this was done we were released from the scene and went 10-8 from the call.

Report by Chris Charley

311 Aerial 311

04:47:17

04:43:38

04:50:13

10:47:28

| Staff ID\Staff Name | | Activity | Rank | Position | Role |
|---------------------|-------------------|-----------------|-------------|----------|--------------|
| BARGMAN, J | Bargman, Jared L. | Fire At Scene | Engineer ba | Engineer | Fire Fighter |
| LEE, K | Lee, Kevin | Alien Atl Mcene | Captain | Captain | Captain |

| 07009 | IA | 2 | 4 | 2020 | 1 | 20-0009423 | 000 | Exposure | Responding Units/Personnel

 Unit
 Notify Time
 Enroute Time
 Arrival Time
 Cleared Time

 311 Aerial 311
 04:42:17
 04:43:38
 04:50:13
 10:47:28

Staff ID\Staff Name Activity Rank Position Role

Unit Narrative

Units were dispatched for a possible commoncial structure fire at Maple lanes bowling center. Call had been initiated by station I due to a walk in at the station. Due to the location and multiple calls about smoke coming from the structure, 300 advised dispatch to upgrade response to full assignment for commercial building fire.

04:42:17 Unit 311 was dispatched for a commercial building fire at 2608 University Ave. (Maple Lanes bowling center)

04:50:13 Unit 311 arrived on scene ad was advised by command to stage apparatus at the "Alpha/Delta" corner of the building and prepare to put aerial ladder into operation if needed. After 311 staged, I requested a supply line from the next arriving engine. Unit 302 was then requested to respond. Unit 302 was advised to establish a supply line from the corner of University and Ansborough Ave. to 311.

05:04:57 Unit 302 arrived on scene and laid large diameter supply to 311. I advised command that the door on the Alpha/Braya corner was standing open. Command then advised 311's crew and 302 to advance a hand line late the door on the Alpha/Delta corner for fire attack. Due to the size of the structure we took 200' of 2 ½' line and advanced into the structure. Upon entering the conditions inside this area were moderate smoke banked down about half way to the floor with almost no heat. We met up with 301's crew about half way down the Delta side of the structure. Due to the conditions we decided to back the line out of the structure and then advance in the same door but to go the left through the kitchen and move along the Alpha side of the building. We then met up with 304's crew about 2/3's of the way down the Alpha side to just inside the main entrance. They had located some heavy fire conditions in this area but could not find the seat of the fire.

Command was then updated about the location and the interior conditions. I then advised to remove our hand line and reposition it to advance in the main entrance. While this was being done, I then unlocked the main entrance door and propped them open. The double glass doors from the main entrance going to the Pro shop area were closed and locked. Since the seat of the fire was inside this area, the right side door was broken to gain access into the pro shop. I then unlocked the left side of the door way for better access. Heavy fire was then located at the far end of this area. The 2 ½" line was used to knock the fire down. At this time I had to leave the area to refill my SCBA. Unit 302's crew took over the operation in this area.

After refilling my SCBA, command advised to use 311 to recon the roof of the building. PM Kyle Fuller was assigned to assist with this operation. Once above the roof we could see that the roof was still intact with smoke only coming out of the vents. There was an area above the main entrance that had some discoloration and possible sagging just inside the roof line. At this time it was still dark outside and we had no generator to use the lighting.

We remained on scene until we were relieved by Captain Mahood and Eng. Floyd.

Reported by Captain Kevin Lee

C Shift narrative:

Upon arrival at station one 311 engineer Floyd and Captain Mahood were directed to respond to the scene in unit 334 which had just been returned to service from public works. Upon

07009 IA 2 4 2020 1 20-0009423 000 Responding Units/Personnel

arrival on scene C shift crew met with 8 shift crew and relieved them after receiving a pass-down on tool usage and their actions taken. 311 C shift crew then reported to the command car for assignment, where Cpt Mahood was directed to take his crew on the roof and check on the openings crews had made there on 8 shift. Finding no active extension in the openings on the roof, 311 was then directed to go interiorly and check for hot spots with the crew from 305. Inside the Pro Shop are 311 and 305 worked on minor hot spots and extension in the Alpha side wall near the main entrance. When that was contained 311 was directed back to the roof to investigate stoke coming from the roof capping system along the parapet walls. With the help of mixed crews from 306 and 305, 311 peeled back steel flashing to determine that the smoke was cold smoke trapped inside the layers of the roofing system and was not a hazard or extension of the fire. With fire operations under control and the aerial no longer needed 311 was returned to service and quarters to clean and restore gear on the apparatus.

Reported by Captain Ryan Mahood

| | | | | 5 | |
|-------------------------------|----------------|-------------|-----------------|-----------|--|
| 324 Fire Marshall | 07:45:40 | 07:45:50 | 07:56:01 | 17:05:36 | |
| Staff ID\Staff Name | Activity | Rank | Position | Role | |
| FERGUSON, C Ferguson, Chris J | Envestmate | Fire Marsha | | | |
| | | | | | |
| 326 FIRE INSPECTOR | 07:45:41 | 07:45:50 | 07:56:01 | 17:05:36 | |
| Staff ID\Staff Name | Authio hey | Rank | Position | Role | |
| WELIVER, B Weliver, Brock J | tion at late | Licutenant | | | |
| | | | a.a. | | |
| 334 Medic 334 | 04:42:17 | 04:43:43 | 04:45:14 | 11:02:51 | |
| Staff ID\Staff Name | Antivity | Rank | Position | Role | |
| PAUL, D Paul, Dwight D. | Files At Scene | Paramedic 1 | Paramedic | Paramedic | |
| ZIMMERLY, M Zimmerly, Michael | Fire At Scene | Paramedic 1 | Paramedic | Paramedic | |
| Unit Narrative | | | | | |

334 dispatched for a commercial building fire.

Upon arrival, heavy smoke showing. 334 crew assisted Engine 304 with pulling a 2 1/2 inch hand-line to entry point on the Bravo side of the structure. 334 crew then assisted Engine 306 with extending a 2 1/2 inch leader limits to an entry point at the Bravo/Charlie corner. 304 requested assistance pulling hose limit into Bravo side entry point. 334 Zimmerly assisted pulling hose approximately 50 feet into the structure and immediately exited the structure. 300 assigned 334 to assist with primary search of the rear of the building at the entry point on the Bravo/Charlie corner. Heavy smoke found in the mechanical room behind the lanes, but no fire found. While walking through the mechanical area, it is worth noting that the machines that set the pins on the lanes were operating. Ceiling tiles pulled along the Bravo side of the structure looking for fire extension with no active fire or burning insulation found. 334 then assigned to RIT. 334 then assigned to set up rehab station. Medic unit 334 moved to Alpha side of the structure to provide rehab location. 334 remained in a rehab role until C-Shift 334 Medic Van Dyke assumed control of Medic unit 334 at approximately 0800 hrs.

B-Shift 334 Medic Michael Zimmerly

This is a state of the state of

WATERLOO FIRE RESCUE Page 12 07009 02/04/2020 20-0009423

| | 2 4 L | 2020 1 | 20-000942 | | Responding Personnel | |
|---------------------------|-------|------------------|-----------|-----------|-------------------------|------|
| Staff ID\Staff Name | Unit | Activity | Position | Rank Pay | Scl Hrs HrsPd | Pts |
| LUCK, T Luck, Troy L | 300 | FX Fire At Scene | | ВС | 7.06 7.06 | 0.00 |
| PETERSEN, BEN Petersen, | 300 | FX Fire At Scene | | BC LT- | 1 7.06 7.06 | 0.00 |
| AGBESE, O Agbese, Onyotse | 301 | FX Fire At Scene | FF | FF-4 | 6.71 6.71 | 0.00 |
| ERNST, S Ernst, Scott | 301 | FX Fire At Scene | FE | ENG-BS | 6.71 6.71 | 0.00 |
| HELLER, J Heller, Josh | 301 | FX Fire At Scene | LT | LT BS | 6.71 6.71 | 0.00 |
| ANDERSON, N Anderson, | 302 | FX Fire At Scene | FP | PM-8 | 6.83 6.83 | 0.00 |
| HESS, S Hess, Samuel J | 302 | FX Fire At Scene | FP | FF-8 | 6.83 6.83 | 0.00 |
| WEBER, B Weber, Benjamin | 302 | FX Fire At Scene | | FF-1 | 6.83 6.83 | 0.00 |
| BJERKE, J Bjerke, Jerry | 303 | FX Fire At Scene | FE | PM-8 | 2.11 2.11 | 0.00 |
| HENNESSY, B Hennessy, Bob | 303 | FX Fire At Scene | | FF-8 FF-8 | 8 2.11 2.11 | 0.00 |
| MEISER, D Meiser, David | 303 | FX Fire At Scene | FP | PM-6 | 2.11 2.11 | 0.00 |
| HANSEN, R Hansen, Randall | 304 | FX Fire at Scene | FF | FF-4 | 7.29 7.29 | 0.00 |
| PALMER, J Palmer, Jeff | 304 | PX Fice At Scene | FE | ENG-10 | 7.29 7.29 | 0.00 |
| SPENCE, M Spence, Michael | 304 | FX Fice 2 Scene | FF | FF-8 | 7.29 7.29 | 0.00 |
| PHILLIPS, J Phillips, | 305 | FX Fire At Scene | FE | ENG-BS | 5.84 5.84 | 0.00 |
| ROTH, C Roth, Christopher | 305 | FX Fire At Scene | FF | FF-4 | 5.84 5.84 | 0.00 |
| SAMUELSON, B Samuelson, | 305 | FX Fire Ar Scene | LT | LT BS | 5.84 5.84 | 0.00 |
| HEYERHOFF, S Heyerhoff, | 306 | FX Fire At Scene | FE | ENG-10 | 6.60 6.60 | 0.00 |
| MAHOOD, M Mahood, Marc | 306 | FX Fire /L Scene | FF | FF-8 | 6.60 6.60 | 0.00 |
| STEWART, B Stewart, Brian | 306 | FX Fire At Scene | FP | FF-1 | 6.60 6.60 | 0.00 |
| BARGMAN, J Bargman, Jared | 311 | FX Fire At Scene | FE | ENG-BS | 6.09 6.09 | 0.00 |
| LEE, K Lee, Kevin | 311 | FX Fire At Scene | CP | CP | 6.09 6.09 | 0.00 |
| FERGUSON, C Ferguson, | 324 | 10 Investgate | | FM PM | 4 4.23 4.23 | 0.00 |
| WELIVER, B Weliver, Brock | 326 | IO Investgate | | LT BS PM | 4 4.23 4.23 | 0.00 |
| PAUL, D Paul, Dwight D. | 334 | FX Fire At Scene | PM | PM-1 | 6.34 6.34 | 0.00 |
| ZIMMERLY, M Zimmerly, | 334 | FX Fire At Scenc | PM | PM-1 | 6.34 6.34 | 0.00 |

Total Personnel Hours: 153.58 Total Participants: 26

| 0.000 | IA DD TYYY IA 2 4 2020 1 20-0009423 L tata * Incident Date * Extent Number * E | Delete NFIRS - 1S Supplemental |
|---------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|
| K 1 Person/Enti | ty Involved | Phone Number |
| Check this box if same address as incident location. Then skip the three duplicate address lines. | Rich Mr., Mr., Mrs. Pirmt Some 2608 Number Profix Screen or Gislay Maplewood Lanes Post office box IA 50701 States Zip Code | Suffix Street Type Suffix |
| K 2 Person/Enti | ty Involved | 319 - 319 - 4153 |
| Check this box if same address as incident location. Then skip the three duplicate address lines. | Linda Eighme Nt., Ms., Mrs. First Name Number Pretix Strass = blance Waterloo Post office box IA 50703 - State Zip Gode | Suffix Street Type Suffix |
| K3 Person/Enti | ty Involved | 319 - 231 - 4554 Phone Number |
| Check this box if same address as incident location. Then skip the three duplicate address lines. | Fran Eighme | Suffix Street Type Suffix |
| K4 Person/Enti | ty Involved | Phone Number |
| Check this box if same address as incident location. Then skip the three duplicate address lines. | Tim Bicholas Mr., Mr., Mr., Ellar hamm IN Dant Name Name | Suffix Street Type Suffix |
| K 5 Person/Enti | ty Involved | Phone Number |
| Check this box if same address as incident location. Then skip the three duplicate address lines. | No. Mrs. Pirst Nume 12: Lost Name Number Frotis Person of Males Post office box 12: 7509 | Suffix Street Type Suffix |
| | State Ztr Code | NFIRS-11 Revision 6/9/98 |

MM DD YYYY NFIRS - Involvement 07009 IA 2 | _ 4 2020 20-0009423 000 User Fields Incident Date i: ident Mumber Exposure State FDID

Involvement Name:

Wilson, Ryan

Involvement

Type:

Manager

Owner:

Occupant:

-

Involvement Name:

Beschorner, Zac

Involvement

Type:

Owner:

Occupant:

Χ

Involvement

Involvement

Type:

Owner:

Occupant:

Χ

Eighme, Rich

Name:

Involvement Name:

Eighme, Linda

Involvement

Type:

Owner:

Occupant:

Χ

07009

MM DD YYYY NFIRS - Involvement 20-0009423 000 07009 IA 2 4 2020 User Fields FDID State Incident Date Judicient Number Exposure

Involvement

Name:
Eighme, Fran

Involvement

Type:

Owner:

Occupant:

Χ

Involvement
Name:
Nicholas, Tim

Involvement
Type:
Maintenance

Owner:

Occupant:

WATERLOO FIRE RESCUE 07009 02/04/2020 20-0009423