

Fire Incident Report - NERIS

Details Reported by Dispatch

Automatic Alarm: No

Incident Number: 26-020

Dispatch Timeline

Call Arrival: 01/30/2026 06:42:00

Call Answered: 01/30/2026 06:42:00

Call Created: 01/30/2026 06:42:00

Location as Reported by Dispatch

Dispatched Location: 623 West Street Main

City, State, Postal Code: Safford, 85546

Unit Response as Reported by Dispatch

Unit Responses		
Dispatch Unit NERIS ID	Dispatch Unit Call Sign	Dispatch Unit Staffing Reported
FD04009348S000U005	C-1	1
FD04009348S000U000	C-2	1
FD04009348S000U001	113	4
FD04009348S000U006	111	6
FD04009348S000U003	115	3

Incident Details

Incident Date: 01/30/2026

NERIS Incident ID: FD04009348|26-020|1769780520

Incident ID: 26-020

Primary Incident Fire - Structure Fire - Room and Contents Fire
Type:

Response Mode: Emergency

Location Use Type: Commercial - Office / Other Technical Services Incident Location In Use: Yes

Location Used as Yes
Intended:Incident Action Suppression - Structural Fire
Taken: Suppression - Interior; Forcible Entry; Investigation; Provide Equipment - Provide Light; Provide Equipment - Provide Special Equipment; Salvage And Overhaul; Ventilation - Positive Pressure; Ventilation - Positive Pressure - Post SuppressionIncident Action Action
Type:

Incident Timeline

First Unit Arrival: 01/30/2026 06:42:00

In Service Date 01/30/2026 08:43:00
Time:

Incident Location

District:**Zone Number:****Incident Location**
Type:**Incident Location:** 623 West Street Main**City, State, Postal Code:** Safford, 85546-

Incident Location Cross Streets

Incident Authorization

Member Making Report - Signature: Anderson, Patrick (7572)

Officer in Charge - Signature: Anderson, Patrick (7572)

Incident Narratives

Primary Narrative: Upon arrival, smoke was observed coming from the roof of Rose Hill Wellness, located at 623 W. Main Street. The windows were blackened by smoke and warm to the touch. At 625 W. Main Street, a water flow alarm was sounding, with water flowing from the front door and window. Smoke was visible through the window, and the glass was warm to the touch.

I directed Ladder 111 (L-111) to make entry into both 623 and 625 W. Main Street and to set a ladder for roof access. Engine 113 (E-113) established a hydrant connection to supply L-111 and accessed the roof. E-113 crews reported no fire conditions on the roof, only light smoke.

Crews from L-111 found no fire in 625 W. Main Street, only smoke and water damage resulting from an activated sprinkler head. Crews did locate fire damage with minimal active flame in 623 W. Main Street. The fire was located in the fourth office from the front of the building at 623 W. Main Street.

Crew member Richards entered the room via the hallway and reported that the top half of the door was missing due to fire damage. While examining the room with a thermal imaging camera (TIC), Richards observed very little visible flame; however, a pot located in the center of the room appeared super-white on the TIC, indicating it was significantly hotter than most other objects in the room.

Crew members Larson, Richards, and Garcia reported that a massage table was positioned just left of center in the room, directly above the pot, which was used to heat stones for massage therapy. Burn patterns on the massage table indicated the fire originated beneath the table.

The rooms on the east side of 625 W. Main Street were connected to 623 W. Main Street. One sprinkler head in the front of 625 W. Main Street activated due to heat, with no fire damage noted in that area. Two electrical breakers were found tripped at 623 W. Main Street.

Positive pressure ventilation was conducted to clear smoke from 625 W. Main Street, 623 W. Main Street (Rose Hill Wellness), and 615 W. Main Street (Trends Salon).

Damage assessment was as follows:

625 W. Main Street: Smoke and water damage

623 W. Main Street: Fire, smoke, and water damage

615 W. Main Street: Smoke damage only

The cause of the fire is undetermined and remains under investigation at the time of this report.

Unit Response

Incident Unit Responses

Incident ID: 26-020

Incident Date:

01/30/2026

Unit NERIS ID	Unit Call Sign	Unit Staffing Reported	Apparatus Action
FD04009348S000U005	C-1	1	Command and Control - Establish Incident Command
Incident Unit Response Personnel			
Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level
Anderson, Patrick (7572)	Chief		
FD04009348S000U000	C-2	1	Command and Control - Safety Officer Assigned
Incident Unit Response Personnel			
Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level
Archuleta, John (7556)	Asst. Chief		
FD04009348S000U006	111	6	Suppression - Structural Fire Suppression - Interior ; Forcible Entry
Incident Unit Response Personnel			
Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level
Richard, Tristan (7997)	Firefighter	Crew 5	
Green, Nathan (7564)	Captain	Officer	
McGaughey, Steve (7246)	Engineer	Driver	
Vaughn, Jacob (7993)	Firefighter	Crew 4	
Garcia, Cameron (8000)	Firefighter	Crew 6	
Larson, Alex (7890)	Lieutenant	Crew 3	
FD04009348S000U001	113	4	Provide Services - Provide Apparatus/Water ; Ventilation - Positive Pressure - Post Suppression
Incident Unit Response Personnel			
Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level
Wray, Anthony (7999)	Firefighter	Crew 4	
Tilley, Sam (8001)	Firefighter	Crew 3	
Windsor, Casey (7882)	Lieutenant	Officer	
Cavanaugh, Mark (7989)	Engineer	Driver	
FD04009348S000U003	115	3	Ventilation - Positive Pressure - Post Suppression
Incident Unit Response Personnel			
Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level
Ball, Jeff (7718)	Captain	Crew 3	
Torres, James (7734)	1st Aid Captain	Officer	
McGaughey, John (7513)	Engineer	Driver	
T-7 (Station)	2		
Incident Unit Response Personnel			
Personnel Name/ID	Personnel Rank Or Grade	Personnel Role	Personnel Level
Marquez, Carlos (7968)	Firefighter		
Torres, Brianna (7960)	Firefighter		

Fire Details

Fire Location Type: Structure

Fire Investigation Yes
Needed:

Fire Water Supply: Hydrant Greater 500

Fire Investigation Investigated On Scene Resource
Type:

Fire Suppression Medium Diameter Fire Hose
Appliance:

Structure Fire

Fire Progression Yes
Evident:
Fire Floor Of Origin: 1
Structure Fire Unable To Be Determined
Cause:
Fire Damage Type: Moderate Damage

Fire Arrival Smoke Showing
Condition:
Fire Room Of Origin Office
Type:

Risk Reduction

Smoke Alarm Present
Presence:
Smoke Alarm Type: Unknown
Smoke Alarm Yes
Working:
Smoke Alarm No Occupants to Notify
Operation:

Fire Alarm Presence: Present
Fire Alarm Type: Automatic
Fire Alarm Failed to Operate
Operation:

Other Alarm Not Present
Presence:

Fire Suppression

Fire Suppression Present
Presence:

Fire Suppression Types

Fire Suppression Type

Wet Pipe Sprinkler System

Fire Exposure Details

Exposure Type	External Exposure Item	Exposure People Present	Fire Exposures				Exposure Location Use Type	Fire Exposure Location
			Exposure Damage	Exposure Location in Use	Exposure Location Use Intended			
External Exposure	Structure	No	Minor Damage	Yes	Yes		Commercial - Office Other Technical Services	625 West Street Main
External Exposure	Structure	No	Minor Damage	Yes			Commercial - Office Other Technical Services	615 West Street Main