# Jekyll Island Lighting Survey

Obs.- Mark Dodd

Date- 7/11/2018

Time- 9:00-1135 PM

Survey Area- Jekyll Island, Holiday Inn to south water tower

| Violation | Location | Fixture | No. of Fixtures | Comments |
|---|---|---|---|---|
| Wavelength/ Not shielded | Putt-Putt Golf | Clubhouse Cupola | 1 | |
| Wavelength/ Not shielded | great dunes pavilion bathrooms | Flourescent ceiling fixture | 1 | The square openings near the top of the wall should have louvers installed |
| Wavelength/ Not shielded | Tortuga Jacks | string lights on the rafters of the tiki hut | 36? | |
| Wavelength/ Not shielded | Tortuga Jacks | unshielded string lights around restaurant door | 6? | |
| Wavelength? | Tortuga Jacks | flood on exterior of tiki hut roof | 3 | |
| Wavelength/ Not shielded | Tortuga Jacks | walkway bollards | 2 | louvers are broken out |
| Wavelength/ Not shielded | Westin | Interior room lights over door | 5 | Interior light fixture over individual room door entrances can be seen on beach. |
| not shielded | Jekyll Ocean Club | Pool lights | 4 | pool lights should be shielded and dimmed by 50% |
| | | | | |
| Wavelength?/unshielded | Holiday Inn- North Bldg. 1st floor/2nd floor | room entrance fixtures | 20 | Entrance fixtures on the north side of building facing restaurant |
| Wavelength?/partially shielded | Holiday Inn- North Bldg. end-2nd floor entrance light | partially shielded light over door | 1 | |
| Wavelength/unshielded | Holiday Inn-- lobby 3d floor | ceiling fan fixtures | 3 | |
| Wavelength/unshielded | Holiday Inn- Restaurant | Interior ceiling cans | 4 | closure of blinds will take care of this issue |
| Wavelength?/not shielded | Holiday Inn- Restaurant | partially shielded string lights-porch | 6 | |
| Wavelength | Holiday Inn-South Bldg. 1st floor | room entrance fixtures | 26 | Ocean facing rooms includes 4 fixtures in breezeway |
| Wavelength/ uplight | Holiday Inn | uplights on Holiday Inn sign | 2 | |
| Wavelength/ not shielded | West of Holiday Inn building | cobra head sreetlight | 2 | |

The convention center was not active on the night of the survey. All lights were turned off. We were not able to assess convention center compliance with the ordinance

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

| | | | | |
|---|---|---|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |