

Case IH 1200 Series Planter Performance Kits

DO YOU HAVE THESE PROBLEMS?

- Skips and poor seed spacing
- Excessive seed disc wear and vacuum problems



OPTION 1: Optimize and Improve Factory Meters

- Machine Meter Cover to reduce seed disc wear and improve vacuum seal.
- Paddle Agitator aggressively pulls seed into meters to eliminate bridging in corn and sunflowers.

OPTION 2: Install Precision Planting VSet Meters

- Utilize factory drive system (chain or cable)
- Plant any size seed with no adjustment



1/4 the cost of
VDrive system



Planter Parallel Arm Repair

- Machine out your arms and install larger bushings
- Solid cross bar for upper arms prevents flexing
- Available for any planter

John Deere eSet Soybean Disc

- 90-hole single row holes spaces soybeans just like corn
- Save time switching meters just change disc to go from corn to beans
- A must for lower populations



DAKOTA PRECISION PLANTING

For information and
pricing contact:

Keyle: 605-396-7418

Columbia, South Dakota

www.DakotaPrecisionPlanting.com