



Form: PFD Annual
Inspection

Pocatello Fire Department

Occupancy: Highland High School

Occupancy ID: 1523 - 27

Address: 1800 Bench RD Pocatello ID 832014999

Inspection Type: Annual

Inspection Date: 11/28/2022

By: Bullock, Dean S (0703)

Time In: 09:00

Time Out: 16:00

Authorized Date: 12/15/2022

By: Bullock, Dean S (0703)

Inspection Description:

Annual Fire Inspection Form 2020

Inspection Topics:

Address

Have address posted on outside of business with 4" letters

Must post address

Status: PASS

Notes:

Knox Box in place where required and key works for doors

If required

Status: PASS

Notes:

Construction Features

No Holes in walls/ceiling

No holes

Status: PASS

Notes:

Ceiling tiles in place

Ceiling Tiles in Place

Status: FAIL

Notes: B16- replace damaged and missing ceiling tiles.

Electrical Equipment

No extension cords being used as permanent wiring

No extension cords being used as permanent wiring

Status: FAIL

Notes: Room C28- Piggy back surge protectors.

C29- Illegal splitter for two microwaves. Please provide more power on different circuits.

C42- Replace zip cords with surge protectors.

B3, B4, B10, B20, B23- Piggy backed surge protectors.

B16, B71- Need surge protectors.

No multi plug adapters being used (surge protectors are acceptable)

No multi plug adapters being used (surge protectors are acceptable)

Status: FAIL

Notes: Art Room- Cannot have surge protectors piggy backed.

Space heaters need to be plugged directly into the wall-Rm C-44, B-70, Indian special services room.

Electrical panel boxes, receptacles, light switches have proper covers and/or closed
Electrical panel boxes, receptacles, light switches have proper covers and/or closed

Status: PASS

Notes:

No storage blocking electrical panel box (36" clearance)

No storage blocking electrical panel box (36" clearance)

Status: PASS

Notes:

Exits & Fire Escapes

No padlocks on exit doors while occupied

No padlocks on exit doors while occupied

Status: PASS

Notes:

Exit doors swing in direction of travel

Exit doors swing in direction of travel

Status: PASS

Notes:

Panic hardware is operational

Panic Hardware Operational

Status: PASS

Notes:

All fire alarm panel clear from obstructions

All fire alarm panel clear from obstructions

Status: PASS

Notes:

All pull stations not obstructed from view

All pull stations not obstructed from view

Status: PASS

Notes:

Fire rated, self-closing doors close completely and latch (not propped open)

Fire rated, self-closing doors close completely and latch (not propped open)

Status: PASS

Notes:

Fire Alarm System is current, operable and inspected

Fire Alarm System is current, operable and inspected

Status: FAIL

Notes: Fire alarm panel in trouble mode. Needs to be serviced ASAP.

All exit aisles clear from obstructions

All exit aisles clear from obstructions

Status: FAIL

Notes: Doorway leading onto stage needs to be cleared.

Emergency lighting is operable (required if >50)

Emergency lighting is operable (required if >50)

Status: FAIL

Notes: Emergency lighting not operable at the back of the auditorium, Room B19, B15,

Exit signs illuminated (if more than 1 exit is required)

Exit signs illuminated (if more than 1 exit is required)

Status: FAIL

Notes: Exit signs need to be updated or replaced.

Carbon Monoxide Detectors tested regularly

Carbon Monoxide Detectors tested regularly

Status: ADVISED

Notes: Need CO detectors in furnace rooms if gas is used to heat the building.

Fire Extinguishers and Extinguishing Systems

Extinguisher mounted on wall

Extinguisher mounted on wall

Status: PASS

Notes:

Extinguisher has annual test by outside company or extinguisher is new

Extinguisher has annual test by outside company or extinguisher is new

Status: PASS

Notes:

Extinguisher not obstructed from view

Extinguisher not obstructed from view

Status: PASS

Notes:

Fire Lanes

Fire Lanes properly marked and maintained

Fire Lanes properly marked and maintained

Status: PASS

Notes:

Fire Lanes are not obstructed

Fire Lanes are not obstructed

Status: PASS

Notes:

Housekeeping

Outside Dumpsters are not within 5' of building or overhangs

Outside Dumpsters are not within 5' of building or overhangs

Status: PASS

Notes:

Combustibles are not stored next to heating source(s) (i.e Water heaters)

Combustibles are not stored next to heating source (i.e Water heaters)

Status: FAIL

Notes: Paper needs to be removed off of lights in rm B9. Paper can be moved 1-2 ft away on ceiling.

Housekeeping inside and outside of building is orderly

Housekeeping inside and outside of building is orderly

Status: FAIL

Notes: Drama storage in outside building needs cleaned badly. Walkway must be clear of combustibles. Will reinspect in January.

No storage in front of exits

No storage in front of exits

Status: FAIL

Notes: Exit doorways on stage need to be clear.

Combustibles are not stored in storage room

Combustibles are not stored in storage room

Status: FAIL

Notes: Recycling bins need to be moved out of the classroom

No storage within 18" of sprinkler heads (except against wall) IFC 2018

No storage within 18" of sprinkler heads (except against wall) IFC 2018

Status: PASS

Notes:

No storage within 24" of ceiling in unsprinklered areas (except against wall)

No storage within 24" of ceiling in unsprinklered areas (except against wall)

Status: PASS

Notes:

Restaurants/Assembly

Occupancy Load posted in the building

Occupancy Load posted in the building

Status:

Notes:

Sprinkler and Standpipe Systems

Sprinkler System is current, operable, and has been inspected annually/ 5 Year

Sprinkler System is current, operable and has been inspected annually

Status: PASS

Notes:

Fire Department caps on FDC

Fire Department caps on Fire Department Connections

Status: PASS

Notes:

Fire department connections/standpipe are not blocked

Fire department connections/standpipe are not blocked

Status: PASS

Notes:

Extra sprinkler heads in sprinkler cabinets

Extra sprinkler heads in sprinkler cabinets

Status: FAIL

Notes: Spare sprinkler heads needing in sprinkler cabinet. Sprinkler cages may need to be replaced in the weight room.

Sprinkler heads are not painted

Sprinkler heads are not painted

Status: FAIL

Notes: Eschuteons missing in Rm B-65, B-3 by Hallway? by door 6 needs eschuteons. Room B23 has branches blocking the sprinkler head and touching light fixtures.

Storage and Handling of Flammable Liquids/Gas

Compressed gas cylinders must be secured

Compressed gas cylinders must be secured

Status:

Notes:

Fuel shut off familiarization (gas stations)

Fuel shut off familiarization (gas stations)

Status:

Notes:

Kitchens

Have required Class K extinguisher for Deep Fryer

Have required Class K extinguisher for Deep Fryer

Status:

Notes:

Hood system is inspected as required

Hood system is inspected as required

Status:

Notes:

Nozzles cover appliances

Nozzles cover appliances

Status:

Notes:

Hood System is free of grease and is clean

Hood System is free of grease and is clean

Status: ADVISED

Notes: Not used but it is clean

Additional Time Spent on Inspection:

Category	Start Date / Time	End Date / Time
Notes: No Additional time recorded		

Total Additional Time: 0 minutes

Inspection Time: 420 minutes

Total Time: 420 minutes

Summary:

Overall Result: FAIL

Inspection did not pass. Violation(s) noted.

Inspector Notes: Stage curtains in the lunchroom do not have a fire rated tag. Curtains must be fire rated for use.

Closing Notes:

Order to Comply: As such conditions are contrary to law, you are hereby required to correct same upon receipt of this notice. An inspection to determine whether you have complied will be conducted on or after the date listed above. Failure to comply with the foregoing order before the date of re-inspection may render you liable to penalties provided by law for such violation(s). Every day that a violation exists may constitute a separate count of the violation(s).